

Remington Arms Co., Inc.
Product Service
Legal Case #:8293

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
290922	11/30/2012	12/7/2012	12/7/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Lincoln Scheels All Sports	Lincoln	Scheels	2960 Pine Lake Rd	Lincoln	NE	68516		W 402-420-9000

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		Unknown
S	Fired when rechambering 2nd round	Concern:1008 Fired on Bolt Closing		
C				
12/27/12 Per note with rifle, fired when rechambering 2nd round.cm				

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/300 WIN MA	25807	G6584500	KA	5/23/2006 2:46:50 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	HENRYS TACKLE LLC	STK CART. BOOT	U			

CONCERN:FIRES CHAMBERING SECOND ROUND

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Can offer to replace TPA, clean, test fire at 1/2 normal cost						
Repair/Replacement Cost	Repair/Replacement Date					

12/27/12 Per Ilion, could not duplicate concern. Trigger assm dirty and some rusting. Can offer to replace TPA, clean, test fire at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/7/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 300 WIN MAG
	Date Code		KA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

Bolt	Shroud	Slightly Worn; Functioning	BRASS WASH AND CHIPS	
	Face	Slightly Worn; Functioning		
	Handle	Slightly Worn; Functioning		
	Stop	Slightly Worn; Functioning		
Extractor	Condition	Slightly Worn; Functioning		
	Cut Condition	Slightly Worn; Functioning		
	Ext/Eject Test	False		
Locking	Block Condition	---Select---		
	Lug Condition	Slightly Worn; Functioning		
	Notch Condition	---Select---		
Overall	Exterior Condition	Slightly Worn; Functioning		
	Stock Condition	Slightly Worn; Functioning		
	Fore End Condition	---Select---		
Receiver	Condition	Slightly Worn; Functioning		
	Bulged	False		
Safety	Description			
	Function	Like new; Functioning		
	Sub-Assembly	Non-ISS		
Sear	Lift	---Select---		
	Notch	Slightly Worn; Functioning		False
	Tests	Test Fired		
Feeding Test	False			
Trigger	Condition	Slightly Worn; Functioning	DIRTY,LITE RUSTING	
	Pull	---Select---	4.5#	
	Altered	False		
	Sub-Assembly	M/700 Non-Bolt Lock		
Non-Remington Components	Description		STK CART. BOOT	

REPAIR TAG

PRODUCT 306

C

DATE PROMISED

DATE RECEIVED

CUSTOMER

Don C. Savier

ADDRESS

3012 Laredo Dr

CITY, STATE

Lincoln NE

PHONE

402 310-7268

Remington 700

30X41in

in G6584500

Gun fires upon re-chambering
second Rd.

DATE WORK COMPLETED

TOTAL

LINCOLN SCHEELS ALL SPORTS

2960 Pine Lake Road Lincoln, NE 68516
(402) 420-9000 Fax (402) 420-9162

Associate Name:

Serial Number:

G6584500

Model: 700



RE00290922

8293

24"
KAS/06
4.5#
.009

could not duplicate concern.
T.A. dirty & some rusting.
can offer to replace TPA, clean
& test fire at 1/2 normal
cost.

Q

RECEIVED
DEC 10 2012

BY:.....





