

Remington Arms Co., Inc.
Product Service
Legal Case #:8023

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
284897	10/9/2012	10/10/2012	10/10/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Tim	Littell	4466 Shay Rd	Kingston	OK	73439		H 580-564-0529 E timlittell@yahoo.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006	Altered Adjustments or Components		Unknown
S	Has fired on safe	Concern:1005 Unexplained Discharge Safe ON		
C				

10/23/12 Per note on SR, rifle has fied on safe.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	n/a	A6293959	CI	4/28/1976
Date Purchased	Where Purchased	Accessories	Original Owner			
	BAL SYDNEY AUSTRALIA		U			

CONCERN: FSO

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test at BLSM program price						

Repair/Replacement Cost	Repair/Replacement Date
66.44	10/23/2012

10/23/12 Per Ilion, trigger assm set screws altered. Trigger not returning properly. Replace TPA, clean, test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		10/10/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 270 WIN
	Date Code		CI
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown		

	Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING PROPERLY WILL FOLLOW DOWN
	Pull	---Select---	5.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

 frmREInquiry - Repair Inquiry

Repair Number:	RE00284897	Serial: A6293959 Model 700 Center Fire Caliber: 270 Produced: 03/05/1981 SKU: 20000	Repairman:	
Verify Repair	High Priority	8023	Status:	New 9/27/2012 3:28:11 PM

ADDRESS INFORMATION					
Customer		Received from	Return To	Received from	
Name:	TIM LITTELL		TIM LITTELL		
Address 1:	4466 SHAY ROAD		4466 SHAY ROAD		
Address 2:		PO Box:		PO Box:	
City:	KINGSTON		KINGSTON		
State:	OK	Zip Code:	73439	Country:	US

FFL:

--	--	--	--	--	--

 01011900

Contact / Condition Problems Estimate History / Status Shipping / Billing

Contact Information	
Phone:	580 564 0529
Fax:	
Email:	timlittell@yahoo.com
Comments:	

Received Condition	
	Good
Condition Notes	
CSR Notes:	Gun is 1976 700. Has fired on safe.

Accessories Received		
Code	Desc	Qty
ADD7	With Stud	2

Refresh Close

T.A. set screws A / ten
ing not returning properly
replace TPA, clean nest under
B.L.P. Con 8 20.6 Q

Serial Number:

A6293959

Model: 700



RE00284897

RECEIVED
OCT 17 2012



