

Remington Arms Co., Inc.  
Product Service  
Legal Case #:6988

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
253528	1/11/2012	12/5/2011	1/12/2012	11/12/2011			

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Tom	Loucks	41 Ichabod Ln	Ballston Spa	NY	12020		C 518-361-3645

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S	Concern:1007 Fired on Safe Release			
C FSR				

12/5/11: Customer called in. He stated he was using rifle recently & had a FSR. No damage, No injury, No incident date. His father told him he saw something on TV & needed to send the rifle to Remington for exam. df

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	6749212 KY	5/1/1974
Date Purchased	Where Purchased	Accessories	Original Owner		
	JERRYS SPORT SHOP OLYPHANT PA004300	TWO PIECE BASE	N		

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$29					

12/5/11: Mailing ARS & forms. Box order# 1280851. df 1/16/12: Per Ilion - Could not duplicate concern. TA dirty & sticky, set screws altered. Replace TA, clean & test fire under BLM - quote. Customer apprvd & pd quote. df

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/12/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	APPEARS ACTION UNDER STOCK IS COVERED WITH GREASE, MAKING PARTS SLUGGISH
Barrel	Description		22" 3006 SPRG
	Date Code		KY
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while		

	Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	HAS BEEN BEDDED
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.006
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,STICKY
	Pull	---Select---	6#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

# Remington®

22"  
KYS/7  
6#  
.006

6988

December 5, 2011

Tom Loucks  
41 Ichabod Ln.  
Ballston Spa, NY 12020  
Phone: 518-361-3645

Ref: # 6988, Model 700, Serial # 6749212

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and service request. A box will arrive separately.

**Please include a copy of this letter and service request to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service".** Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely,  
Dell Fulcher  
Consumer Affairs Administrator  
Remington Arms Co., LLC  
Phone: 1-800-243-9700 press 0 and ask for ext 8686  
Fax: 336-548-7872

RECEIVED  
JAN 10 2012

enclosure

BY:.....

could not duplicate com  
T.A. dirty & sticky set screws  
altered - Rep by TPA,  
clean + test under BCP  
don't ship  
Quote

6749212

Model: 700



RE00253528

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025  
Phone 800-243-9700 • [www.remington.com](http://www.remington.com)

# Service Request

Remington Service  
PO Box 700

Madison, NC 27025-0700



ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

[www.Remington.com](http://www.Remington.com)

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

<b>Service Request Number</b> SR00005792	<b>Serial Number / Description</b> 6749212 Model 700 Center Fire Caliber: 3006	<b>Date of Request:</b> 12/05/2011 <b>Date Printed:</b> 12/05/2011
<b>Customer:</b> TOM LOUCKS 41 ICHABOD LN BALLSTON SPA, NY 12020 US  Email:	<b>Destination:</b> Arms Services 14 Hoeffer Ave Ilion, NY 13357 US  Email:	

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

## Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

## Service Request Section

Product Service # 6988 - FSR

## Parts And Service Details

Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount
----------	------	-------------	---------------	----------	-------	------	--------

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

**Sub Total:** .00  
**Est Sales Tax:** .00

Print

Reset

Model Number: <u>700 3006</u>		Serial Number: <u>6749212</u>	
Are you the original owner?: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
Name: <u>THOMAS K. LOCKS</u>		Date of Purchase: <u>? Received as Gift</u>	
Address (no PO Boxes): <u>41 NEWBOD LANE</u>			
City: <u>BALLSTON SPA</u>	State: <u>NY</u>	Zip: <u>12020</u>	
Phone (Daytime): <u>518-361-3645</u>		Fax:	
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent)			
E-mail Address: <input type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem and date of occurrence: <u>Weapon Discharged when safety removed to unload Chamber 11-12-11</u>			
500 characters left			
Ammunition Information:			
Manufacturer:		Type:	
Other (i.e. bullet weight/type, shot size powder):			
Handload Information:			
Powder Used:		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	
Firearms Care (Cleaning and Lubrication):			

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

## ARS LABEL REQUEST FORM

DATE:	12/05/2011	Service Request #	SR00005792
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	fulcherdm	email address:	I WILL MAIL LABEL

### Business:

Remington Service  
PO Box 700  
Madison, NC 27025-0700  
[www.Remington.com](http://www.Remington.com)

## LABEL INFORMATION

MAIL LABEL TO:	TOM LOUCKS 41 ICHABOD LN BALLSTON SPA, NY 12020 US SR00005792  Email:
RETURN ITEM TO:	ILN  Arms Services



4XX596 DEC 6, 2011 ALL CURR USD 1 OF 1  
SVC GND COM ACT WT 10.0 LBS  
TRACKING# 1Z4XX5969065149981  
REF 1:SR00005792  
REF 2:

HANDLING CHARGE 0.00		SVC T/P USD
SINGLE-PIECE PUB RATE CHRG:		RS 0.50
DV 0.00	COD 0.00	SD 0.00
DC 0.00	DGD 0.00	SP 0.00
AH 0.00	PR 0.00	
TOT PUB CHG 7.94	PUB+HANDLING	7.94

**ATTN: Product Service**







