

Remington Arms Co., Inc.
Product Service
Legal Case #:8061

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
285970	10/17/2012	10/18/2012	10/18/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Jerad	Martinez	640 E. 78th Place	Thornton	CO	80229		

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance			
S Gun fired on safe	Concern:1005 Unexplained Discharge Safe ON		Unknown	
C				

11/2/12 Per note on SR, gun fired on safe; did not know if there had been a trigger job or not.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM REM MA	n/a	6775019	OZ	7/3/1975
Date Purchased	Where Purchased	Accessories	Original Owner			
	WALMART STR 63 WAGONER OK	TWO PIECE BASE	U			

CONCERN:FOS

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	29.44	11/2/2012				

11/2/12 Per Ilion, trigger assm dirty and rusty parts work sluggish. Replace TPA, clean, test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		10/18/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		24" 7MM REM MAG
	Date Code		OZ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	DIRTY,RUSTY
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,RUSTY PARTS WORK SLUGGISH WILL FOLLOW DOWN
	Pull	---Select---	5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

Service Request

Remington Service

PO Box 700

Madison, NC 27025-0700



ATTN: product service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

2411
0276
54
1008

Service Request Number: SR00029998
Serial Number / Description: 6775019
Model: 700

8061

Date of Request: 09/24/2012
Date Printed: 09/24/2012

Customer:
JERAD MARTINEZ
640 E. 78TH PLACE
THORNTON, CO 80229 US

Destination:
Arms Services
14 Hoefler Ave
Ilion, NY 13357 US

Email:

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION


Service Request Section

gun fired on safe; did not know if there had been a trigger job or not.

Serial Number:

6775019

Model: 700



RE00285970

Qty
Needed

Warranty

Price Disc Amount

RECEIVED
OCT 25 2012

BY:

T.A. Dirty & Rusty parts
work sluggish replace
TPA, clean test under
BLP Cond 20. +

Q

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total: .00
Est Sales Tax: .00
Grand Total: \$.00





