Remington Arms Co., Inc.
Product Service
Legal Case #:8350

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 292597 12/12/2012 12/13/2012 12/13/2012 X

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Incident Ted McKelvey 9050 Maple Grove Rd. Hastings MI 49

49058 H 517-852-0073

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4013 Broken or Missing Parts S FSR Concern:1007 Fired on Safe Release

Concern:1007 Fired on Safe Release

Unknown

C

SR# 36838: Service Request Section - Customer states the rifle fires when the safety is moved to fire position. df

Firearm Information

Mfg.TypeModel/Ga.SKUSerialBbl.DOMRemingtonML/BA700ML/50 CAL27580ML062514 CR 4/11/1997

Date
Purchased Where Purch

Where Purchased Accessories Original
Owner

POINT SPORTING TWO PIECE BASE, AFT MKT 209

GOODS CO PRIMER KIT

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700ML/ML/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Date Cash Date
Settlement APV APV

Per Ilion - Repair @ n/c

Repair/Replacement Repair/Replacement Cost Date

\$34

12/19/12: Per Ilion - Connector is broken. Replace TA, clean & check over at n/c. df

Examination[Remington/ML/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/13/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO ·
Cause	4013	Broken or Missing Parts	CONNECTOR IS BROKEN
	Description		24" 50 CAL SS

i	1	•	
Barrel	Date Code		CR
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Select	AFT MKT
	Shroud	Select	
	Face	Select	
	Handle	Slightly Worn; Functioning	
	Stop	Select	
	Exterior Condition	Slightly Worn; Not Functioning	ACTION DIRTY
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	]
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning	
	Tarta	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	CONNECTOR BROKEN
	Pull	Select	N/A
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE,AFT MKT 209 PRIMER KIT

## Service Request

## Remington Service PO Box 700



Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number SR00036838

Serial Number / Description

ML062514

Customer:

Model 700ML RIFLE Caliber: 50

**PO**MCKELVEY

9050 MAPLE GROVE ROAD HASTINGS, MI 49058 US

Email: Phone # 517-852-0073

Date of Request:

11/29/2012

11/29/2012 Printed:

Destination:

Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

Service Request Section

Customer states the rifle fires when the safety is moved to fire position.

Will not Five Caps Consistatly

Mr. Ted McKelvey 5050 Maple Grove Rd Hastings, MI 49058-8734

arranty

Disc Amount

I do not have a receipt of

this gin as IT was a gift to

me from family

Sincordy

Tel Matteley.

ML062514

CONNECTOR IS Broken Rep. TPA, clopes checkouls # 230145

he item(s)

Sub Total: Est Sales Tax:

.00 .00

**Grand Total:** 

\$.00