

Remington Arms Co., Inc.
Product Service
Legal Case #:8353

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
292619	12/12/2012	12/13/2012	12/13/2012				

Customer Information

Type	Business First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident	Al	Miller	8525 Ooltewah Georgetown Rd.	Ooltewah	TN	37363		H 423-344-2795 E amiller@meadowviewbaptist.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S FSR	Concern:1007 Fired on Safe Release			
C				

SR# 37385 - Customer stated the gun will discharge when moving from Safe to Fire. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	6468146	WU	8/1/1971
Date Purchased	Where Purchased	Accessories	Original Owner			
	DAVIDSON SUPPLY GREENSBORO, NC	TWO PIECE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$29					

12/19/12: Per Ilion - TA dirty & sticky. Set screws altered. Replace TA, clean & test under BLM - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/13/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4006	Altered Adjustments or Components	IMPROPER MAINTENANCE
Barrel	Description		22" 3006 SPRG
	Date Code		WU
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.009
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY, STICKY TRIG SLUGGISH
	Pull	---Select---	6#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

frmREInquiry - Repair Inquiry

Repair Number: RE00292619

Serial: 6468146 Model 700 Center Fire Caliber: 3006
SPRG

Repairman:

Verify Repair

Status: New 12/4/2012 10:43:16 AM

8353

ADDRESS INFORMATION

Customer

☒ Received from

Return To

☐ Received from

Name: AL MILLER

AL MILLER

Address 1: 8525 OOLTEWAH GEORGETOWN RD

8525 OOLTEWAH GEORGETOWN RD

Address 2: PO Box:

PO Box:

City: OOLTEWAH

OOLTEWAH

State: TN

Zip Code: 37363

Country: US

TN

Zip Code: 37363

Country: US

FFL:

01011900

Contact / Condition Problems Estimate History / Status Shipping / Billing

Contact Information

Phone: 423 344 2795

Fax:

Email: amiller@meadowviewbaptist.com

Comments:

373 85

Received Condition

Good

Condition Notes

CSR Notes:

STATES THAT THE GUN WILL DISCHARGE WHEN MOVING THE S TO F.

Accessories Received

Code	Desc	Qty
A007	With Stud B Y:	2
A016	Scope Base	2

RECEIVE
DEC 19 2012

Refresh


Close

T.A. Dirty sticky set screws altered leg. TPAClean & test under BLP on B 20.1 Q

Serial Number:

6468146

Model: 700



RE00292619

THURSDAY, DEC 13 2012 3:45 AM

THURSDAY, DEC 13 2012

3:45 AM

22" was 8/71
64
.009



