Remington Arms Co., Inc. Product Service Legal Case #:8222

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 290646 11/28/2012 11/29/2012 11/29/2012

Customer Information

Last Name Type Business First Name Street City State Zip Contact Age Incident Ralph More 121 LINCOLN CIRCLE MARYLAND 12116 H 607-432-8737

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

PΙ

PD Cause: 4015 Improper Maintenance S FSR Concern:1007 Fired on Safe Release

Unknown

C

Customer brought gun to Ilion. Customer alleged FSR. df

Firearm Information

Mfg. Type Remington CF/BA

Model/Ga. **SKU** 700/3006 SPRG n/a

Serial Bbl. DOM

Date Purchased

Where Purchased

Accessories

Original Owner

6755915 PY 6/1/1974

SCOPE, SEE THRU MOUNTS, SLING

U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Date Cash Date APV APV

Per Ilion - Quote to repair under BLM

> Repair/Replacement Cost

Repair/Replacement Date

\$31

12/3/12: Per Ilion - TA has partially dried & sticky lube residue causing parts to bind & work sluggish. Replace TA, clean & test under BLM quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/29/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4015	Improper Maintenance	
ВагтеІ	Description		22" 3006 SPRG
	Date Code		РУ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructe	d	-
	Muzzle/Crown	Slightly Worn; Functioning	

	Condition		<u></u>
Bolt	Firing Pin	Slightly Worn; Functioning	SLUGGISH
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning	
	T	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY PARTS WORK SLUGGISH WILL FOLLOW DOWN
	Pull	Select	6.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE, SEE THRU MOUNTS, SLING

the against the common security of the growth of the growt

Receipt Of Firearm(s) Delivered to the Plant for Repair Firearm Checked For Live Ammunition [1] Driver's License ID# REDACTED Employee (Y) (N) Customer Name (Print) RALHA C. Mon State Zip Ziv Phone Number (NZ) - MTZ-Manufacturer_P Firearm Description Model _ Cal./Ga. -Serial Number 6756915 Stock/ Fore-end Condition - circle the description (Excellent, Good, Fair, Poor, Fancy, Plain, Synthetic, Wood) Metal Condition - circle the description [Excellent, Good, Fair, Poor, Fancy, Plain Stainless Steel) TICICY lube 12151 du c CAUSING Comments on Stock/ Fore-end condition _ PARTS TO BIND+ work sluggish Comments on Metal condition _____ Barrel Type (VT. Rib; Plain; Deer; Stainless Steel) Barrel length Nep 1 71 B Clean No ST UNIDER List additional accessories: IE Scope, Sling Oun case and description; BC) Ron \$ 20. Customer request: _ F S R Return Process Return to Clark St. Ent. [Return via UPS [] By signing this receipt the person delivering the firearm understands to be the only person to receive the firearm upon completion of repairs. BY:---k Up Verification vered the above described firearm to the lawfully possess a firearm in New York State. e the same who delivered Date returning the firearm

Security Copy - White

Model:

Arm Service Copy - Yellow

Customer Copy - Pink





