

Remington Arms Co., Inc.
Product Service
Legal Case #:8282

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
291487	12/4/2012	12/5/2012	12/5/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		William	Naumuk	12694 Dingman Rd	Townville	PA	16360		E naumuk@windstream.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components			Unknown
S	Fired when removing safety Concern:1007 Fired on Safe Release			
C				

12/20/12 Per note on SR, wants safety modification, gun fired when safety was taken off.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl	DOM
Remington	CF/BA	700/6MM REM	n/a	A6378132	RI	11/10/1976
Date Purchased	Where Purchased	Accessories	Original Owner			
	GOPHER SHOOTERS FARIBAULT MN	BOTTOM HALF SEE THRU MOUNTS	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash	Reim.	Cash	
				Settlement	Date	Date	
					APV	APV	
Per Ilion, replace TPA, clean, test at BLSM program price							
	Repair/Replacement Cost	Repair/Replacement Date					
	29.44	12/20/2012					

12/20/12 Per Ilion, trigger assm and set screws altered. Trigger not returning properly. Replace TPA, clean, test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/5/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 6MM REM
	Date Code		RI
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.007
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		BOTTOM HALF SEE THRU MOUNTS

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700 F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

2211
REI 11/76
254
100%

Service Request Number
SR00036730

Serial Number / Description
A6378132
Model R784

8282

Date of Request: 11/28/2012
Date Printed: 11/28/2012

Customer:
WILLIAM NAUMUK
12694 DINGMAN ROAD
TOWNVILLE, PA 16360 US

Destination:
Arms Services
14 Hoefler Ave
Ilion, NY 13357 US

Email: naumuk@windstream.net

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section

WANTS SAFETY MODIFICATION GUN FIRED WHEN SAFETY WAS TAKEN OFF

T.A. dirty + set screws ALT.
Trig. not set properly
Ap. TPA, clean & test under
BCR Cor & 20 + Q

Parts And Service Details

Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount
----------	------	-------------	------------	----------	-------	------	--------

11/29/12

REMINGTON!

1. COULDN'T GET THE MOUNT BASES OFF - THEY SHOULDN'T GET IN YOUR WAY.

2. SORRY, BUT I DON'T HAVE MY RECEIPT FROM 1977!

T H A N K S

RECEIVED
DEC 10 2012

Bill Naumburg

Serial Number:

A6378132

Model: 700



RE00291487

Sub Total: .00
Est Sales Tax: .00
Grand Total: \$.00





