Remington Arms Co., Inc. Product Service Legal Case #:7150

Case Information

RE# Date Opened Date Opened (PS) **Date Closed Incident Date** Pre Lit Obsolete

257887 2/8/2012 12/27/2011 2/9/2012

Customer Information

Type Business First Name Last Name Street City Zip Contact State Age 1220 Western Ave H 701-331-0765 Incident Ron Nowacki Grafton ND 58237

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause: 4006 Altered Adjustments or Components

S Fired on safety release

Concern:1007 Fired on Safe Release

Unknown

12/27/11 Per call from Ron, he is the original owner of this 700 and about 2 seasons ago it fired on safety release twice.cm

Firearm Information

Mfg. Remington Type

Model/Ga.

SKU n/a

Serial Bbl. DOM

Date Purchased

CF/BA Where Purchased 700/3006 SPRG Accessories

Original Owner

6844649 XZ 12/1/1975

OUTDOOR SPTS HQ DAYTON OHIO

TWO PIECE BASE

Y

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement

Reim. Date Cash Date

APV

Per Ilion, replace TPA, clean, test at BLSM program price

Repair/Replacement Repair/Replacement Cost

Date

30.40

2/15/2012

12/27/11 Mailing ARS.cm 2/15/12 Per Ilion, trigger assm dirty, set screws altered. Replace TPA, clean, test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		2/9/2012
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	IMPROPER MAINTENENCE
	Description] .	21" 3006 SPRG
	Date Code]	XZ
	Bore Plugged	False	
Barrel	Bulged	False]
	Fired	False]
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning]
	Firing Pin	Slightly Worn; Functioning	· ·

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7150&Type=Case

2/15/2012

	Shroud	Slightly Worn; Functioning	·
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Dossinos	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.008
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY. WILL FOLLOW DOWN
	Pull	Select	4.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

Service Request

Remington Service PO Box 700

Parts and Repairs: P:800-243-9700/F:336-548-7801

Madison, NC 27025-0700 www.Remington.com

12/

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

,0 o/

Service Request Number | Serial Number | Description

SR00007700

Customer:

RON NOWACKI 1220 WESTERN AVE GRAFTON, ND 58237 US

Email: Christy

Date of Request: Date Printed:

12/27/2011 12/27/2011

Destination: Arms Services

14 Hoefler Ave Ilion, NY 13357 US

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Parts And Service Details

Type

Description

Qty Needed

c Amount Disc

FEB 1 5 2012

BY:----

T.A. d. 12ty, setschens altered. Typhic TPA, clean restanded BLP Con & 20.+

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total: Est Sales Tax: .00

.00

Model Number: 700 BDL	Serial Number: 684 4649
Are you the original owner?: X YES NO	
Name: RON NOWACK: 0	Date of Purchase:1974
Address (no PO Boxes): 1380 Wes	Term AUE
City: Grafton	State: 100 Zip: 58237
Phone (Daytime): 701-331-0765	Fexi
E-mail Address:(if e-mail address is provided, notification	of receipt and shipment will be
sent)	
E-mail Address:	the second of th
I would like to receive tuture e-mail updates from Rer	nington.
Please describe your problem and date of occurrence	
IT HAPPENED ON Two	Separate Ocassion's
When I WENT TO TA	
The Chamber when I	Switched From
.14	Gb- Clear The Round
IT Fired	
Transport	
Also For Your INForm	ATION T HAD WITH SULTE
IN A Number of years Ago F 500 GUNSMITH CUT My" OFF En- characters left Glass D 11 The G	or Dipple on End of Barrel I
500 GUNSMITH CUT by OFF En-	1 And Re crowned Ash Also
OIHSS Dadded The D	AS Vou &CAY See 1) MAS Becm
Well Ahen C	are of I Polish The STOCK Two co Befor
Manufacturer: Federal	Typs: Priemon: BTSP
Other (i.s. bullet weight/type, shot size, powder):	55r.
·	
Handload Information:	
Powder Used:	Powder Weight:
Case/Hull Used:	Primer Used:
Bullet Type/Shot Siza:	Reloader Used;


Fireerms Care (Cleaning and Lubrication):	
Brand of cleaning solution used: Hoppes NC.9	
How often do you clean the bore? (Months or Number of rounds) B. Fore And AFTer Huntings	?ASS#
How often do you clean the action? (Months or Number of rounds) Before And After How Ting	
How diten do you dean the trigger assembly? (Months or Number of rounds)	
Brand of Jubricani used: Hoppes No. 9.	
How often do you lubricate the bore? (Months or Number of rounds) Before And AFTen Huntime	
How often do you lubricate the action? (Months or Number of rounds) Before And AFTON HUNTING	
How often do you lubricate the trigger assembly? (Months or Number of rounds)	
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?	
YES 1 NO	
When was the last time that your firearm was serviced by a Remington authorized	
repairmen/gunsmith?) W. eu e/2	
What were the services performed?)	
Remington Arms Co., Inc.	
Atin: Arms Service Division	
14 Hoefier Avenue	
Illon, NY 13357	
(S) WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.	
:: Record the serial number of your firearm before sending it. :: Pack your firearm for seriety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper	
tit Province a ratium angress on haro the diffice and inside the dox. Animments wilhous a brader	
return address will be refused.	

ARS LABEL REQUEST FORM

12/27/2011	Service Request #	SR00007700
1	WEIGHT PER PACKAGE:	10 LBS
mitchelles	email address:	Christy.Mitchell@remington.com
	Remington Service PO Box 700 Madison, NC 27025-0700	
	1	1 WEIGHT PER PACKAGE: mitchelles email address: Remington Service PO Box 700

LABEL INFORMATION		
MAIL LABEL TO:	RON NOWACKI 1220 WESTERN AVE GRAFTON, ND 58237 US SR00007700	
	Email: Christy	
RETURN ITEM TO:	ILN	
	Arms Services	





4XX596 DEC 28, 2011 ACT WT 10.0 LBS #PK 1 SVC GNDCOM BL WT 10.0 LBS
TRACKING# 1Z4XX5969067091913 ALL CURRENCY USINEF 1:SR00007700 REF 2: ALL CURRENCY USD

HANDLING CHARGE 0.00 FRT: 3RD SVC T/P USD RS 0.60 SHIPMENT PUB RATE CHARGES: DV 0.00 DC 0.00 AH 0.00 TOT PUB CHG 10.27 COD 0.00 DGD PR 0.00 0.00 ROD 0.00 PUB+HANDLING 10.27 10.27

