

Remington Arms Co., Inc.
Product Service
Legal Case #:7585

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
264774	4/13/2012	4/16/2012	4/16/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Collin	O'Neill	2503-112th Ave. East	Edgewood	WA	98372		H 253-826-0103

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Unintentional discharge	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown
C				

Customer sent rifle in w/note. He stated he had an unintentional discharge. No report of injury or damage. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM08 REM	25616	C6584480	WK	8/13/1990
Date Purchased	Where Purchased	Accessories	Original Owner			
	ELLETT BROTHERS	TWO PIECE BASE	Y			

CONCERN: UNINTENTIONAL DISCHARGE

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair						
	Repair/Replacement Cost	Repair/Replacement Date				

4/19/12: Per Ilion - Could not duplicate concern. Can offer to replace TA, clean & test fire @ 1/2 normal cost - quote. Customer approved & paid quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/16/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 7MM08 REM MR
	Date Code		WK
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select--	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	--Select--	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	--Select--	.013
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	--Select---	4.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

April 5, 2012

7585

2211
WIK/90
4.5#
013

Repair Dept.

Enclose 7mm/08, I AM ORIGINAL OWNER.

HAVE UNINTENTIONAL DISCHARGE, please
check - Replace TRIGGER AND SET TO
3 3/4 LBS. - ALSO FRONT TIP OF STOCK
IS RIDING BARREL HARD -

Rem 700 - Ser #C6584480

COLLIN O'NEILL
2503 - 112TH AVE. EAST
EDGEWOOD, WN. 98372

PH. 253-826-0103

Serial
Number:

C6584480

Model: 700



RE00264774

RECEIVED
APR 19 2012

BY:.....

could not dup. concern
can offer to rep. TPA, clean
& test AT 1/2 NORM COST
Quote





