

Remington Arms Co., Inc.  
Product Service  
Legal Case #:8323

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
292133	12/10/2012	12/11/2012	12/11/2012				X

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Gregg	Peck	701 N. 15th St.	Broken Arrow	AR	74012		H 918-251-2340 E peck@partisonmetalfab.com

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4013 Broken or Missing Parts		Unknown	
S FSR	Concern:1007 Fired on Safe Release			
C				

SR# 36793 - Reason for Return: Trigger pull is out of factory specs. Service Request Section: Gun fires without pulling the trigger. df

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	ML/BA	700ML/50 CAL	27572	ML098046	DR	9/15/1997
Date Purchased	Where Purchased	Accessories	Original Owner			
	SPORTS SOUTH INC	AFT MKT 209 PRIMER KIT	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Repair at n/c						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$34					

12/13/12: Per Ilion - Connector is broken. Replace TA & check over at n/c. df

## Examination[Remington/ML/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/11/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4013	Broken or Missing Parts	CONNCECTOR BROKEN
Barrel	Description		24" 50 CAL
	Date Code		DR
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	---Select---	AFT MKT
	Shroud	---Select---	
	Face	---Select---	
	Handle	Slightly Worn; Functioning	
	Stop	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	CONNECTOR BROKEN
	Pull	---Select---	N/A
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		AFT MKT 209 PRIMER KIT

**● 中国书画函授大学肇庆分校建校二十周年纪念册**

[www.Remington.com](http://www.Remington.com)

24"  
DR 9/9-  
~~24"~~

8323

M127 - TRIGGER PULL IS OUT OF FACTORY SPECS

gun fires without pulling the trigger

Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount
----------	------	-------------	---------------	----------	-------	------	--------

ML098046

Model: 700ML



RE00292133

connector is broken.

Replace TPA & check over.

AT N/C

# 230145

SHIPPED DEC 13 PAID

Sub Total:	.00
Est Sales Tax:	.00

**Grand Total:** \$ .00

<b>Model Number:</b> 700ML		<b>Serial Number:</b> ML098046	
<b>Name:</b> Greg Peck		<b>Date of Purchase:</b> Appx. 1999	
<b>Address (no PO Boxes):</b> 701 n 15th Street			
<b>City:</b> Broken arrow		<b>State:</b> ok	<b>Zip:</b> 74012
<b>Phone (Daytime):</b> 918-639-1043		<b>Fax:</b> 918-251-1439	
<b>E-mail Address:</b> peck@pattisonmetalfab.com			
<b>Please describe your problem:</b>			
<p>When the gun is on safety and your ready to push the safety up to fire the gun discharges when the safety is pushed up. In other words your finger is nowhere near the trigger but the gun will discharge when the gun is taken off safety.</p>			
264 characters left			
<b>NOTE:</b> Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			
<input type="checkbox"/> <b>WARNING:</b> DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. <b>THIS IS A VIOLATION OF FEDERAL LAW.</b> IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.			
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.			

AK-01

Pattison Precision Products  
Phone: 918-251-9967  
Fax: 918-251-1439

**Question Reference #121120-000081**

**Product Level 1: Other**

**Date Created: 11/20/2012 02:55 PM**

**Last Updated: 11/21/2012 10:58 AM**

**Status: Waiting**

----- We hope that this information will be helpful to you.  
If we can be of further assistance, please contact us at 1-800-243-9700, M-F, 9am-5pm EST. Remington  
Arms Co. -- America's Oldest Gunmaker 870 Remington Drive, Madison, NC 27025 1-800-243-9700 or  
1-336-548-8700--FAX: 1-336-548-7801 Visit us in Remington Country at <http://www.remington.com/>  
REMEMBER, FIREARMS SAFETY DEPENDS ON YOU! Whether you are a beginner or an advanced  
user, our new Safety Section is a must for everyone. <http://www.remington.com/safety> -----  
----- [---001:002408:28144---]