

Remington Arms Co., Inc.
Product Service
Legal Case #:7342

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
256446	1/27/2012	1/30/2012	1/30/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Larry	Peidle	260 South Oakdale Ave	Hermitage	PA	16148		H 724-981-4501 E klpeidle@msn.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S	Fired on safety release			
C	Concern:1007 Fired on Safe Release			

2/8/12 Per note on SR, per consumer, gun fired when he flipped the safety off.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	A6650874	DQ	9/19/1978
Date Purchased	Where Purchased	Accessories	Original Owner			
	JOHNS SPT GDS CANTON OH		U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test fire at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	66.44	2/8/2012				

2/8/12 Per Ilion, could not duplicate concern. Trigger assem very dirty. Replace TPA, clean and test fire at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/30/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		22" 3006 SPRG
	Date Code		IDQ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.009
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	---Select---	7#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

Madison, NC 27025-0700

Parts and Repairs: P-800-243-9700/F-336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

221
Dag/7
7#
100c

Service Request Number SR00010195	Serial Number / Description A6650874 Model 700 Center Fire	<u>7342</u>	Date of Request: 01/18/2012 Date Printed: 01/18/2012
Customer: LARRY PEIDLE 260 SOUTH OAKDALE AVE HERMITAGE, PA 16148 US Email: klpidle@msn.com		Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US Email:	

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return
M240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section
PER CONSUMER, GUN FIRED WHEN HE FLIPPED THE SAFETY OFF.
SNP PROGRAM

Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount
----------	------	-------------	------------	----------	-------	------	--------

Serial Number:

A6650874

Model: 700



RE00256446

RECEIVED
FEB 02 2012

BY:

could not disp. cov.
Til. very dirty, replace
TPA, clean x x x + under
BCP Sn # 20.1

Quote

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total	.00
Est Sales Tax	.00
Grand Total	\$.00





