Remington Arms Co., Inc.
Product Service
Legal Case #:8038

				Legal (Case #:8038						
Case Inform	nation										
RE# 286987		Opened 5/2012	Date Opened 10/15/201	. ,	Date Closed 10/26/2012	Inciden	Date	Pr	e Lit	Lit	Obsolete
Customer I	nformatic	חמ									
			Last Name	Stre	et	City	State	Zip	Age	C	ontact
Incident		Larry	Prior			Vew Florence		•	•		
incident Inf	Farmation	•	1 1 1 2 2			.,				••.	V > - F
			<u>_</u>	odos		Danair Fet	Modi	nol Two	o êm or	nt Mad	liaal Stati
 PI	istini <u>s</u> —		· · · · <u>- · -</u>	oues		"vēhāti toi"	Menn	cai ile	Ame	if ivien	iičai Žisti
PD											
Fires or	n safety			Not Duplicate Concern		Unknown					
S release		Conce	m:1007 Fired	on Sate Rele	ease						
С											
			ought this rifle				med it,	it will :	fire so	metime	s when th
afety is rel	eased. He	has never se	nt it to be inspe	ected since h	e's owned it.	cm					
Firearm Inf	·a-mation										
		Tr.		Mod	el/Ga.	CVII		Serial		DLI	DOM
Mf Remin	_		ype 7/BA		REM MA	SKU n/a		_	4149	Вы. DM	DOM 9/1/196
Date Pu	_		on Purchased	Accessories		Original Owner		_			1 7111170
Date I ul	chasca	Where I	ui chasca		CE BASE	N					
CONCERN	I: FSR										
Other Produ Settlement	ucts Infor	mation - Non	e Defined								
		•		Remingto	on/700/CF/B	A					
Sett	lement	Rele	ase of Claims	Rele	ase Date	Reimburse	ment (Casl Settlen		Reim. Date APV	Date
-	replace T st at BLS am price										
	-	Repai	r/Replacemen			t					
			Cost	-	Date						
10/16/10 24			29.44		1/2012	n i mai			DI GI		
price.cm	lailing Ab	RS.cm 11/1/12	Per Ilion, cou	ld not duplic	cate concern.	Replace TPA	, cican,	test at	BLSN	1 progra	am
Examination	n∏Remins	gton/CF/BA]								_	
	Part		Sub-l	Part]	Code		Ī	C	ommer	ıt
			Sub-l Examiner	Part		Code		В.Т	C		ıt
		ļ.	Examin e r	Part		Code		-	AVIS	3	it
Examinatio	Part			Part		Code		-		3	it

PrintDisplay Page 2 of 2

	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		24" 7MM REM MAG SS
	Date Code	1	DM
	Bore Plugged	False	
Barrel	Bulged	False	=
	Fired	False	
	Fired while Obstructed		-
	Muzzle/Crown Condition	Slightly Worn; Functioning	7
	Firing Pin	Slightly Worn; Functioning	-
··-	Shroud	Slightly Worn; Functioning -	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	7
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Missing	REC'D LESS STK
	Fore End Condition	Select	
n	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.006
Sear	Notch	Slightly Worn; Functioning	
Tests		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	DIRTY
T-:	Pull	Select	6#
Trigger	Altered	True	SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

Remington.

24" Dm9/6 6#6

%03 y October 15, 2012

Larry Prior 187 Booneslick Rd New Florence, MO 63363

Subject: Case # 8038, Model 700, SR# 31775

Dear Mr. Prior,

I am sorry to hear of the problems you have had with your Remington firearm. Please include a copy of this letter with the rifle as well as the Service Request form. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the product is logged in correctly. Please mark the small ends of the boxes "Product Service". After inspection we will contact you with the findings and recommended resolution.

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell
Consumer Affairs Administrator
Phone: 800-243-9700, ext 8684
com

DECERVE L (CT 3 1 20.2

BY:----

₹164149 |Model: 700

RE00286987

Replace TPA, clearer rest under.
Berhout 20. +

P

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

, Service Request

Remington Service

Sub Total:

Est Sales Tax:

Grand Total:

ATTN: Prod Serv #8038

Parts and Repairs: P:800-243-9700/F:336-548-7801

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s)

being sent based on the conversation with our representative.

Madison, NC 27025-0700 www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service.PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number Serial Number / Description 10/15/2012 Date of Request: SR00031775 164149 Printed: 10/15/2012 Date Customer: Destination: LARRY PRIOR Arms Services 187 BOONESLICK RD 14 Hoefler Ave NEW FLORENCE, MO 63363 US Ilion, NY 13357 US Email: 1 PRIOR (2) WEW FLIREWIE COM Email: Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed. Reason For Return M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION Service Request Section Prod Serv #8038 Parts And Service Details Material Description Warranty Price Disc Amount Needed GUN is going OFF with out Gulling TRIGGER SOMET IMES WHEN SAFETY IS KICKED OFF

.00

.00

ARS LABEL REQUEST FORM

DATE:	10/15/2012	Service Request #	SR00031775	
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS	
REQUESTED BY:	mitchelles	email address:		
·				
Rucinocci				

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

LARRY PRIOR 187 BOONESLICK RD NEW FLORENCE, MO 63363 US

SR00031775

Email:

RETURN ITEM TO:

ILN

Arms Services

4XX598 OCT 15, 2012 ACT WT 10.0 LBS #PK 1 SVC GNDCOM BL WT 10.0 LBS TRACKING# 1Z4XX5969068900988 ALL CURRENCY US REF 1:SR00031776 REF 2: ALL CURRENCY USD

CNS 0.00 FRT: 3RD SVC T/P USD RS 0.50 SHIPMENT PUB RATE CHARGES: DV 0.00 DC 0.00 AH 0.00 TOT PUB CHG 10.22 COD 0.00 DGD 0.00 0.00 ROD 0.00 PUB+HANDLING 10.22 PR

ATTN: Prod Serv #8038





