

Remington Arms Co., Inc.
Product Service
Legal Case #:8279

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
291485	12/4/2012	12/5/2012	12/5/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Herman	Ruple	4440 Homesite Dr	Orion	MI	48359		E hgruple@aol.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Fired without touching the trigger	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown
C				

12/20/12 Per note on SR, check the safety and trigger. This gun fired without touching the trigger.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	6552278	CW	4/1/1972
Date Purchased	Where Purchased	Accessories	Original Owner			
	JOHNS SPTG GD CANTON OH		U			

CONCERN:FIRED WITHOUT TOUCHING TRIG

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	29.44	12/20/2012				

12/20/12 Per Ilion, could not duplicate concern. Trigger assm dirty and set screws altered. Replace TPA, clean, test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/5/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		CW
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.007
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY STICKY
	Pull	---Select---	4#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

Parts and Repairs: P-800-243-9700 F-336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number SR00035660
Serial Number / Description 6552278
Model 700096

8279

Date of Request: 11-20-2012
Date Printed: 11-20-2012

Customer:
HERMAN RUPLE
4440 HOMESITE DRIVE
ORION, MI 48359 US

Destination:
Arms Services
14 Hoedler Ave
Ilion, NY 13357 US

Email: hgruple@aol.com

Email:

—Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

22"
CW 4/72
4#
.007

Reason For Return
M240 - BOLT LOCK SAFETY MODIFICATION


Service Request Section

PLEASE CHECK SAFETY + TRIGGER
THIS GUN FIRED WITHOUT TOUCHING TRIGGER

Parts And Service Details

Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount
----------	------	-------------	------------	----------	-------	------	--------

Serial Number: 6552278
Model: 700



RE00291485

could not dip. concern
J.A. dinky + set screws ALT.
dip TRA, CLEAN test under
BLP Con & 20

RECEIVED
DEC 10 2012

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total:
Est Sales Tax:
Grand Total: \$.00





