PrintDisplay Page 1 of 2

Remington Arms Co., Inc.
Product Service
Legal Case #:7719

Legal Case #:7719 Casc Information RE# Date Opened(PS) **Date Closed** Date Opened **Incident Date** Pre Lit Lit Obsolete 270940 6/8/2012 6/11/2012 6/11/2012 Customer Information Type Business First Name Last Name Street City State Zip Age Contact 2166 Holly Ave. H 530-891-8622 CA Incident Joseph Sandberg Chico 95926 Incident Information Medical Medical Repair Claims Codes Est. Treatment Status ΡI PD Cause:4006 Altered Adjustments or Components Concern:1025 Unexplained Discharge - No Mention of Safety Position Unknown 2 Accidental S Discharges Customer sent gun in w/our repair form. He stated he had 2 accidental discharges. df Firearm Information DOM SKU Bbl. Model/Ga. Serial Mfg. Type 246300 EN 10/1/1966 CF/BA 700/270 WIN Remington n/a **Date Purchased** Where Purchased Accessories Original Owner SCOPE BASE N **CONCERN: 2 ACCIDENTAL DISCHARGES** Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/700/CF/BA Cash Reim. Date Cash Date Settlement Release of Claims Release Date Reimbursement Settlement APV APV Per Ilion - Quote to repair under BLM Repair/Replacement Repair/Replacement Cost Date 6/15/12: Per Ilion - Could not duplicate concern. TA set screws altered. Replace TA, clean & test fire under BLM - quote. Customer approved & paid quote. df Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/11/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	]
Barrel	Description		22" 270 WIN
	Date Code		EN
	Bore Plugged	False	
	Bulged	False	]
	Fired	False	]
	Fired while Obstructed		_

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7719&Type=Case

6/15/2012

PrintDisplay Page 2 of 2

	Muzzlo/Croup Condition	Slightly Worn; Functioning	1
	Firing Pin	Slightly Worn; Functioning	]
	Shroud	Slightly Worn; Functioning	1
Bolt	Face	Slightly Worn; Functioning	Į
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	j
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	]
	Ext/Eject Test	False	
	Block Condition	Select	]
Locking	Lug Condition	Slightly Worn; Functioning	]
	Notch Condition	Select	]
	Exterior Condition	Worn; Functioning	
Overall	Stock Condition	Worn; Functioning	BEDDED,AFT MKT GRIP CAP
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	}
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	]
	Lift	Select	.07
Sear	Notch	Slightly Worn; Functioning	
	T	Test Fired	False
Feeding Test	Tests	False	
<u> </u>	Condition	Slightly Worn; Functioning	SAFETY DETENT CLIP MISSASSM
T-:	Pull	Select	3#
Trigger	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE

	ngton. ENING
	r Instructions ι 000/ m, and then include it with your firearm.)
Model Number: Madel 700	Serial Number: 2 46 300
Are you the original owner?:	M7 brother
Name: JUSEPH R SANDBELT	Date of Purchase: 1968 -1969
Address (no PO Boxes): 7/66 4/4/7	NUP
city: CHICO	State: CALIF Zip: 4597/
Phone (Daytime): 570-191-1672	Fax:
E-mail Address:  Would like to receive future e-mail updates from R	Lemington.
Please describe your problem:	
HAD OVE OF POS	5156 two(2)
accidental discharge	<del></del>
1	
Ammunition Information:	
Manufacturer: RYMING TOWOL Federal	Type:
Other (i.e. bullet weight/type, shot size, powder):	· USe 130 GRAY Bullet
Handload Information:	La contraction of the contractio
Powder Used: Case/Hull Used:	Powder Weight:
Bullet Type/Shot Size:	Primer Used: Reloader Used:
bullet Type/Shot Size:	Reloader Used:
Finance Core (Classical and Laboration).	
Firearms Care (Cleaning and Lubrication):	-01/
Brand of cleaning solution used: KeL 10. 4-	
How often do you clean the bore? (Months or Number of	
How often do you clean the action? (Months or Number of	
How often do you clean the trigger assembly? (Months o	r Number of rounds) , a kt-r Shooting
Brand of lubricant used: Hopp # 9	
T.A. set scheus Altere	JUN 1 4 2012
replace TPA clematest under 3cl Por 820+	BY:
U 1	

Quote

i often do you lubricate the bore? (Months or Number of rounds)often do you lubricate the action? (Months or Number of rounds) often do you lubricate the trigger assembly? (Months or Number of rounds) you re<u>viewed the cleaning and maintenance recommendations on our web site or in our owners manual?</u> iments: en was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? at were the services performed? p your INSURED firearm by either UPS or Parcel Post to: REMINGTON ARMS CO., INC **ATTN: Arms Service Divison** 14 Hoefler Ave - Ilion, NY 13357 **MARNING:** DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE EDEDAT I AW: IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE ss or damage. e the box. Shipments without a proper

Model: 700 RE00270940

sreturned.)
iss or damage.
e the box. Shipments without a prope
st. Remington is not responsible for
purchase insurance from your carrier.

epairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please ude your credit card number and expiration date with your gun)

or Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes I shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, redit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over 1.00 by setting a pre-authorized amount that can be billed to your credit card.







