Remington Arms Co., Inc.
Product Service
Legal Case #:7897

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

280159 8/27/2012 8/30/2012 8/30/2012

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Reporter Scheels Scheels 2101 W 41st St Sioux Falls SD 57105 W 605-334-7767

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause:4038 Could Not Duplicate Concern

Unknown

S Has fired while on safe Concern:1028 Fired With Safe ON

C

9/10/12 Per note with rifle, the owner states that over the past 15 yrs, the gun has fired while on safe.cm

Firearm Information

Mfg.
Remington

Type CF/BA Model/Ga. 700/270 WIN

**SKU** 25771

Serial Bbl. DOM

Date

Where Purchased

Accessories

Original

C6511241 LK 2/28/1990

Purchased

NATIONAL SHOOTING SUPPLIES, INC.

TWO PIECE BASE Owner U

CONCERN:FOS

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims

Release Date

Reimbursement Cash Settlement Reim. Date Cash Date

AP

APV APV

Per Ilion, offer to replace TPA, clean, test at 1/2 normal cost

Repair/Replacement Repair/Replacement

Cost

Date

113.94

9/10/2012

9/10/12 Per Ilion, could not duplicate concern. Trigger assm dirty. Can offer to replace TPA, clean, test at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/30/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7897&Type=Case

9/10/2012

PrintDisplay Page 2 of 2

Cause	4038	Could Not Duplicate Concern	
	Description		22" 270 WIN
	Date Code		LK
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	<b>=</b>
	Ext/Eject Test	False	
<del></del>	Block Condition	Select	_
Locking	Lug Condition	Slightly Worn; Functioning	<b>=</b>
-	Notch Condition	Select	Ħ
	Exterior Condition	Slightly Worn; Functioning	=
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	-Select	7
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	7
	Description		STANDARD SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.013
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	DIRTY
That are an	Pull	Select	5.5#
Trigger	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	<u> </u>
Non-Remington Components	Description	1	TWO PIECE BASE

2101 W 41st St Sioux Falls, SD 57105 Phone (605) 334-7767 Fax (605) 334-8936

August 22, 2012

Remington Arms Co 14 Hoefler Ave Ilion, NY 13357

Manufacturer: Remington

Model: 700

Serial Number: C6511241 Caliber/Gauge: 270 Win Service Order #: 386477

Enclosed is a Remington 700. The owner states that over the past 15 years, the gun has fired while on safe. Please inspect and notify us of the charges for repairing.

Sincerely,

Eileen Fritz

Gunsmith Office Manager

Enclosure

Model:



Meceive? AUG 3 1 2012

could not duplicate concern. T. A. dirty. CAN often to hip bu TPA, clean + 725T AT 1/2 Nopma/ cost





