

Remington Arms Co., Inc.
Product Service
Legal Case #:7693

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
269585	5/29/2012	5/30/2012	5/30/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Seneca Pawn Shop	---	Seneca Pawn Sho	593 W. North 1st St.	Seneca	SC	29678		W 864-882-4188

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S FSR	Concern:1007 Fired on Safe Release			
C				

Dealer sent rifle in. Dealer stated the rifle needs bolt lock safety modification & it has had a FSR. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	B6375357	LC	2/18/1982
Date Purchased	Where Purchased	Accessories	Original Owner			
	K MART ENTERPRIZ NEWMAN GA	SCOPE,SEE THRU RINGS	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$30					

5/31/12: Per Ilion - Could not duplicate concern. TA dirty, set screws altered. Replace TA, clean & test fire under BLM - Quote. df 6/1/12: Dealer called & apprvd quote & paid by CC#. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		5/30/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		LC
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Test Fired	False	
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	---Select---	5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE,SEE THRU RINGS

7693
*22
LC2/82
5#*

Alice Brandenburg
Seneca Pawn & Variety, Inc.
593 W. North 1st Street
Seneca, SC 29678
(864) 882-4188

May 23, 2012

Arms Services
14 Hoeffer Ave.
Ilion, NY 13357
(800) 243-9700

Dear Sirs:

I am a stocking retailer. The enclosed rifle was returned to me for repair.

Remington 30-06cal Rifle
Model: 700
Serial: B6375357

Service Request Number: SR00019995

Problem: 1) Loads and unloads in "fire" position only. (Bolt lock safety modification.)
2) Intermittantly fires when disengaging the safety.

RECEIVED
MAY 31 2012

Please repair or replace it. Thank you.

Sincerely,

Alice Brandenburg

Alice Brandenburg
thangselling@yahoo.com

Serial Number

B6375357

BY: _____

Model: 700



RE00269585

*could not dup. concern
T.A. dirty, set screws altered.
dup. TAA, clean test under
BCP for 20 +*

Quote







