PrintDisplay Page 1 of 2

> Remington Arms Co., Inc. Product Service Legal Case #:7951

Case Information

RE# Date Opened Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 9/17/2012 9/20/2012 9/20/2012 282516

Customer Information

Type **Business** First Name Last Name Street State Zip Contact Age Reporter The Shooter's Sports Center The Shooter's S 4900 6 Mile Rd WI 54302 H 262-681-1040

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PI

PD Cause: 4015 Improper Maintenance Unknown

Hammer drops when bolt is closed

Concern:1008 Fired on Bolt Closing

9/26/12 Per note on SR, hammer drops when the bolt is closed.cm

Firearm Information

Mfg. Model/Ga. SKU Serial Bbl. Type DOM Remington CF/BA 700/300 WIN MA 27482 E6765636 OV 7/29/2001 6:13:39 AM

Date Purchased Where Purchased

Accessories **Original Owner** DICK S SPORTING GOODS TWO PIECE BASE U

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Reim. Date Cash Date Release Date Settlement Release of Claims Reimbursement Settlement APV APV

Per Ilion, replace TPA, clean and test fire at 1/2 cost

> Repair/Replacement Repair/Replacement Cost Date

9/26/12 Per Ilion, trigger and trigger pin rusted and causing trigger to bind between side plates. Replace TPA, clean and test fire at 1/2 cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		9/20/2012
	Product Type		RF
	Action Type		A
	Assigned To]	T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		24" 300 WIN MAG
	Date Code		ov
	Bore Plugged	False	·
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7951&Type=Case

9/26/2012

Bolt			i
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn, Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
Sear	Lift	Select	.017
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG AND PIN RUSTED TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	Select	8#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

Thursday, Sep 30 20 IILASRPRII

MAKOIS

Thursday, Sep 20 2012

6:07 AM





