

Remington Arms Co., Inc.
Product Service
Legal Case #:7785

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
274406	7/13/2012	7/16/2012	7/16/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Sports World Inc		Sports World In	6841 East 41st St	Tulsa	OK	74145		W 918-742-4027

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Discharged when bolt closed on live round	Cause:4038 Could Not Duplicate Concern Concern:1008 Fired on Bolt Closing	Unknown	
C				

7/23/12 Per note with rifle, gun discharged when bolt closed on live round.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/243 WIN	25787	G6626211	XA	12/1/2006 8:15:49 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	SPORTS SOUTH INC	SCOPE BASE	U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, offer to replace TPA, test at 1/2 normal cost						

Repair/Replacement Cost	Repair/Replacement Date

7/23/12 Per Ilion, could not duplicate concern. To restore confidence in rifle, can offer to replace TPA, test at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		7/16/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE

Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 243 WIN
	Date Code		XA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.014
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE BASE

7785

22"
X A12/06
5th
014

N6

Return To Factory

Customer: Sports World, INC.
address: 6841 EAST 41ST STREET
State, City, Zip: Tulsa, OK 74145

Date To Factory : 07/09/2012

Sports World Repair Number : J48385

Package ID Number : 385

Reason For Returning To Manufacturer : GUN DISCHARGED WHEN BOLT WAS CLOSED
ON LIVE ROUND.

Please Note : Please send estimate for repairs to the attention of T.L.
Denton. This firearm should be returned to Sports World, Inc for billing
purposes.

Thankyou,

Claims clerks, please put this note with your paper work for RC #

cc : Manufacturer

Thank you,

Sports World, Inc.
6841 EAST 41ST STREET
TULSA, OK 74145
(918)742-4027

RECEIVED
JUL 19 2012

BY:

G6626211

Model: 700



RE00274406

could not duplicate concern
to restore confidence in rifle
can offer to replace TPA stock at
1/2 normal cost.

Quote





