

Remington Arms Co., Inc.
Product Service
Legal Case #:7304

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
255076	1/19/2012	1/20/2012	1/20/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Kevin	Stewart	103 Fox Ridge Rd	Panama City	FL	32405		E kevindstewart@comcast.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components			Unknown
S	Fired on safety release Concern:1007 Fired on Safe Release			
C				

1/31/12 Per note on SR, gun fires when gun is put on fire.cm

Firearm Information.

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	n/a	A6567602	LQ	2/16/1978
Date Purchased	Where Purchased	Accessories	Original Owner			
	ODENWALD CO WAUCONDA IL	SEE THRU RING MOUNTS	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	30.40	1/31/2012				

1/31/12 Per Ilion, trigger assm dirty and set screws altered. Replace TPA, clean, test fire at BLSM program price.cm *1/31 left age w/quote*

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/20/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 270 WIN
	Date Code		LQ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown	Slightly Worn; Functioning	

<http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7304&Type=Case>

1/31/2012

	Condition		
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.011
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY, TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SEE THRU RING MOUNTS

Service Request

Remington Service
PO Box 700



Madison, NC 27025-0700 ATTN: SMP

Parts and Repairs: P:800-243-9700 F:336-548-7801 www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number / Description SR00009068 A6567602		Date of Request 01.09.2012
Customer: KEVIN STEWART 103 FOX RIDGE RD PANAMA CITY, FL 32405 US		Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US
Email: KEVINDSTEWART@COMCAST.NET		Date Printed: 01.09.2012

7304

22"
LQ2/78
25#
8' 011

850-832-9388

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be rep returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return
M240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section
GUN FIRES WHEN GUN IS PUT ON FIRE

Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount
----------	------	-------------	------------	----------	-------	------	--------

A6567602

Model: 700



RE00255076

RECEIVED
JAN 24 2012

BY:

T.A. dirty & set screws & Hened.
replace TPA, c & AN + test fire
under BLP Ron & 20. +

Quote

Sub Total:	.00
Est Sales Tax:	.00
Grand Total:	\$.00





