

Remington Arms Co., Inc.
Product Service
Legal Case #:7278

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
254438	1/16/2012	1/17/2012	1/17/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Jim	Strange	10675 Esat 850th Ave	Watson	IL	62473		E.j.strange@blmachinedesign.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Fired when the safety was pushed off	Concern:1007 Fired on Safe Release		Unknown
C				
1/30/12 Per note on SR, gun has went off when the safety was pushed off.cm				

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/22-250 REM	20000	A6387332	XI	12/7/1976
Date Purchased	Where Purchased	Accessories	Original Owner			
	LEW HORTON SOUTHBOROUGH MA	SCOPE BASE	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	30.40	1/30/2012				

1/30/12 Per Ilion, could not duplicate concern. Trigger assm set screws altered. Trigger not returning properly. Replace TPA, clean, test fire at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/17/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 22-250 REM
	Date Code		XI
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	HAS AN ADJUSTABLE COMB INSTALLED
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.004
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	TRIG NOT RETURNING PROPERLY
	Pull	---Select---	3#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE

Service Request

Remington Service
PO Box 700

Madison, NC 27025-0700



24"
X 12/76
34
1004

Parts and Repairs: P-800-243-9700/F-336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

Service Request Number SR00008248	Serial Number / Description A6387332 Model 700 Center Fire	Date of Request: 01/03/2012 Date Printed: 01/03/2012
Customer: JIM STRANGE 10675 EAST 850TH AVE. WATSON, IL 62473 US	Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US	
Email: jstrange@blmachinedesign.com	Email:	
Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.		
Reason For Return M240 - BOLT LOCK SAFETY MODIFICATION		
Service Request Section PER CONSUMER, GUN HAS WENT OFF WHEN THE SAFETY WAS PUSHED OFF. SMP PROGRAM		
Parts And Service Details		
Material	Type	Description
	Qty Needed	Warranty
	Price	Disc Amount
<div>Number: A6387332</div> <div>Model: 700</div> <div></div> <div>RE00254438</div> <div>RECEIVED JAN 18 2012 BY: _____</div> <div>could not dup. concern T.A. set screws altered. T119 not met. prop. replace TPA, COAN LTD. R. ne under JCI RON BLO. +</div> <div>THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the</div> <div>Sub Total: .00 Est Sales Tax: .00 Grand Total: \$.00</div>		



1A6387332
Type 700
RE00251436



