

Remington Arms Co., Inc.
Product Service
Legal Case #:8275

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
291311	12/4/2012	12/5/2012	12/5/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Tim	Sweet	10376 Hardwood Trail	Perrinton	MI	48871		E ltsweet2003@yahoo.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Fires when closing bolt	Concern:1008 Fired on Bolt Closing		
C				

12/20/12 Per note with rifle, occasionally firing pin moves forward when locking the bolt.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	20000	6498604	BW	1/1/1972
Date Purchased	Where Purchased	Accessories	Original Owner			
	SLOANS SPTG GD RIDGEFIELD CT		U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Remington/700/CF/BA	
					Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	20.44	12/20/2012				

12/20/12 Per Ilion, could not duplicate concern. Trigger assm dirty and set screws altered. Replace TPA, clean, test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/5/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 308 WIN
	Date Code		BW
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.007
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY, STICKY
	Pull	---Select---	5.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

Service Request

Remington Service

PO Box 700

Madison, NC 27025-0700



22"
BW 1/7
5.5"
100'

Parts and Repairs: P-800-243-9700/F-336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

Service Request Number SR00035477	Serial Number / Description 6498604 Model 700308	8275	Date of Request: 11/19/2012 Date Printed: 11/19/2012
Customer: TIM SWEET 10376 HARDWOOD TRAIL PERRINTON, MI 48871 US		Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US	

Email: LITSWEET2003@YAHOO.COM

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M536 - SAFETY WORKS HARD

- OCCASIONALLY FIRE AND PIV MOVE FORWARD WHEN LOCKING BOLT

Service Request Section

SAFETY MODIFICATION PROGRAM, ALSO CONSUMER WANTS BOLT RE-JEWELLED

- X-MARK TARGET
- BOLT SAFETY UPGRAD


Parts And Service Details

Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount
----------	------	-------------	------------	----------	-------	------	--------

Serial Number:

6498604

Model: 700



RE00291311

could not dup. concerns
T.A. dirty + set screws A/H.
Rep. TPA, clean + test under
BLP Con 20.4

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total:	.00
Est Sales Tax:	.00
Grand Total:	\$.00

RECEIVED
DEC 10 2012

BY:.....

From: RICHARD PUNDERSON (doubleguy@charter.net)
To: ltsweet2003@yahoo.com;
Date: Thu, October 11, 2012 9:00:38 AM
Cc:
Subject: FIREARMSELLER, LLC. Customer Receipt/Purchase Confirmation

Thank you for your order!

Order Information

Merchant: FIREARMSELLER, LLC.
Description: Remington 700 .308, Item # 309421161

Billing Information

Tim Sweet
10376 Hardwood Trail
Perrinton, Mi 48871
ltsweet2003@yahoo.com
989-682-4250

Shipping Information

Item	Description	Qty	Taxable	Unit Price	Item Total
Website Sale	Buy Now	1	N	US \$445.00	US \$445.00
	Customer specified amount				

Total: US \$445.00

Visa

Date/Time: 11-Oct-2012 9:00:37 EDT
Transaction ID: 4797265278







