

Remington Arms Co., Inc.
Product Service
Legal Case #:7474

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
261183	3/8/2012	3/9/2012	3/9/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Tactical Weapon Systems		Tactical Weapon	177 North Main St	Rosholt	WI	54473		

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S	Fired when closing bolt	Concern:1008 Fired on Bolt Closing		
C				

3/26/12 Per note on SR, gun went off while closing bolt.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl	DOM
Remington	CF/BA	700/270 WIN	n/a	6492476	RU	11/1/1971
Date Purchased	Where Purchased	Accessories	Original Owner			
	AMER WHLSE HD LNG BEACH, CA		U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test under BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	30.40	3/26/2012				

3/26/12 Per Ilion, trigger assm dirty and sticky causing trigger to bind and not return properly. Replace TPA, clean and test under BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		3/9/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		22" 270 WIN
	Date Code		RU
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

<http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7474&Type=Case>

3/26/2012

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.009
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY, STICKY TRIG NOT RETURNING PROPERLY WILL FOLLOW DOWN
	Pull	---Select---	6.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

frmRepairMain - FGI Repairs

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System

frmREInquiry - Repair Inquiry

Repair Number: RE00261183 Serial: 6492476 Model 700 270 WIN Repairman:
 Verify Repair High Priority Status: New 2/24/2012 1:27:21 PM

ADDRESS INFORMATION

Customer	Received from	Return To	Received from
Name: TACTICAL WEAPON SYSTEMS		TACTICAL WEAPON SYSTEMS	
Address 1: 177 NORTH MAIN STREET		177 NORTH MAIN STREET	
Address 2: PD Box:		PD Box:	
City: ROSHOLT		ROSHOLT	
State: WI Zip Code: 54473 Country: US		WI Zip Code: 54473 Country: US	

FFL: 01011900

Contact / Condition Problems Estimate History / Status Shipping / Billing

Problems Reported

Code	Desc
M123	FORWARD TO PRODUCT SE...

Problems Found

Code	Desc
------	------

Repair Notes

Repairman's Comments

T.A. dirty & sticky causing trig. to bind & not return properly. Replace TPA, clean w/ test under BLP Ron 8 to +

CSR Comments

GUN WENT OF WHILE CLOSING BOLT

Refresh

Close

6492476

Model: 700



RE00261183

BY:

RECEIVED
MAR 14 2012

22"
124/11/71
6.54
1009







