

Remington Arms Co., Inc.
Product Service
Legal Case #:7539

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
263023	3/28/2012	3/29/2012	3/29/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Targetmaster	---	Targetmaster	255 Wilmington West Chester Pike	Chadds Ford	PA	19317		W 610-459-5400

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S FSR	Concern:1007 Fired on Safe Release			
C				

Dealer sent rifle in & stated that gun will fire on safe release. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	27319	G6330573	PX	6/19/2003 9:26:33 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	JERRY S SPORT INC	TWO PIECE BASE	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair						
	Repair/Replacement Cost	Repair/Replacement Date				

4/9/12: Per Ilion - Trigger & pin rusted & causing trigger to bind. Replace TA, clean & test at 1/2 normal cost - quote. Dealer apprvd quote & charged to open account. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		3/29/2012
	Product Type		RF
	Action Type		A
	Assigned To		T. NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		22" 3006 SPRG
	Date Code		PX
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
Scar	Lift	---Select---	.015
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG AND PIN RUSTED TRIG BINDING
	Pull	---Select---	7.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

frmREInquiry - Repair Inquiry

Repair Number: RE00263023

Serial: G6330573 Model 700 Center Fire Caliber:
3006 SPRG

Repairman:

Verify Repair

High Priority

Status: Repairing 3/28/2012 10:28:49 AM

7539

ADDRESS INFORMATION

Customer

☒ Received from

Return To

☐ Received from

Name: TARGETMASTER

TARGETMASTER

Address 1: 255 WILMINGTON WEST CHESTER PK

255 WILMINGTON WEST CHESTER PK

Address 2: PO Box:

PO Box:

City: CHADDS FORD

CHADDS FORD

State: PA Zip Code: 19317 Country: US

PA Zip Code: 19317 Country: US

FFL:

4/10/2012

Contact / Condition Problems Estimate History / Status Shipping / Billing

BY:

Problems Reported

Code	Desc
M123	FORWARD TO PRODUCT SE.

Repair Notes

Repairman's Comments

7.19g + PIN rusted + crusting
 fail to bind. replace TPA, clean
 + no os at 1/2 normal cost.
 Quote

Problems Found

Code	Desc
------	------

CSR Comments

dealer said when you chamber a round and remove the
 safety the gun will fire without touching the trigger (per
 Joseph @ Target master) 3/28 jmr

Refresh

Close

G6330573

Model: 700



RE00263023

Thursday, Mar 29 2012 4:31 AM

Thursday, Mar 29 2012

4:31 AM

22"
 PX6/03
 7.5"
 1015





