

Remington Arms Co., Inc.
Product Service
Legal Case #:7287

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
253639	1/11/2012	1/18/2012	1/18/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	TP Outdoors		TP Outdoors	101 Mill St	West Monroe	LA	71291		W 318-322-2979

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S	Fired on bolt closing	Concern:1008 Fired on Bolt Closing		
C				

1/31/12 Per note with rifle, need a new trigger. This one is not holding. Fire's when you close the bolt.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	26915	T6215717	XP	12/8/1995
Date Purchased	Where Purchased	Accessories	Original Owner			
	WALTER CRAIG INC	TWO PIECE BASE	U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at 1/2 normal cost						
Repair/Replacement Cost	Repair/Replacement Date					

1/31/12 Per Ilion, trigger assm dirty and sticky. Parts work sluggish. Ca offer to replace TPA, clean, test fire at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/18/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		24" 3006 SPRG SS
	Date Code		XP
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Magazine	Condition	---Select---	
	Box Condition	Slightly Worn; Functioning	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Scar	Lift	---Select---	.010
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY, STICKY PARTS WORK SLUGGISH WILL FOLLOW DOWN
	Pull	---Select---	3.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

7287
24"
x212/9.
3.5"
1010

**TP OUTDOORS
101 MILL ST
WEST MONROE LA 71291
318-322-4474
FAX 388-2979
1-02-2012**

**REMINGTON ARM'S
THIS REM 700 SN.T6215717 NEED A NEW TRIGGER
THIS ONE IS NOT HOLDING FIRE'S WHEN YOU CLOSE THE
BOLT
SEND EST ON REPAIR**

**THANKS
BOBBY JAMES
GUN SMITH**

**CUSTOMER
KEITH STEPHENS
318-366-8407**

**RECEIVED
JAN 20 2012**
BY:.....

T.A. dirty & sticky parts work
sluggish. can offer to replace
TPA, clean & test fire at 1/2
Normal cost.

Quote

T6215717

Model: 700



RE00253639





