

Remington Arms Co., Inc.
Product Service
Legal Case #:7305

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
255018	1/19/2012	1/20/2012	1/20/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		David B	Wartelsky	680 Tranquil Trail	Grand Junction	CO	81507		H 970-245-0214

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Firing pin follows down Concern:1031 Firing Pin Follows Down			
C				

1/31/12 Per letter with rifle, David bought this rifle used 10 yrs ago. He left it with a friend and when he received it back the firing pin would follow down when closing the bolt. He did not have any rounds in the rifle so no damages. He has not been able to duplicate this since.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	n/a	222781	WN	1/9/2002
Date Purchased	Where Purchased	Accessories	Original Owner			
	JERRYS SPORT CENTER	SCOPE BASE	N			

CONCERN: FSR,FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean, test fire at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	30.40	1/31/2012				

1/31/12 Per Ilion, could not duplicate concern. Replace TPA, clean, test fire at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/20/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 308 WIN
	Date Code		WN
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select--	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	--Select--	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	--Select--	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	--Select--	.007
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	--Select--	5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE

7305
1-9-2012
211
W48/66
54
007

Remington Safety program Trigger Arms Services
14 Hoefler Ave
Ilion, New York, 13357

RECEIVED
JAN 21 2012

Remington,

BY:.....

As per my conversation with Greg at customer service I am returning my Remington .308 ADL rifle, SN# 222781 for inspection. I bought this rifle used about ten years or more ago and have hunted with it extensively and have not experienced any problems.

A short synopsis of what happened was: After a trip to Kansas, I returned home to Colorado, but left this rifle with a friend to use in Kansas. He assured me that he did not have time to use it and did not even take it out of the case or use any of the ammunition I had left for him. He just brought it back to Colorado.

So I just went to oil it before returning it to my gun safe. Upon closing the bolt, the firing pin followed. I cocked the bolt and closed it again and the firing fin followed. I then cocked the bolt, engaged the safety, closed the bolt, then took the safety off, at which time the firing pin followed. Had there been a round in the chamber it would have fired. I'm glad my friend did not have time to hunt. And I have not been able to duplicate this since.

Please don't get me wrong, I'm not bashing Remington products. I am a big fan of Remington rifles and shotguns. I currently own four Remington rifles and three Remington shotguns. I would buy another rifle or shotgun, should I need one.

I also used them professionally, as I am a retired police officer from New Jersey and used Remington sniper rifles on the Bergen County Police SWAT Team for years. And I have attended your shotgun armorer's course in Massachusetts.

I just don't want to experience an unintended discharge, which could cause property or bodily injury; therefore I contacted Remington for advice.

If the trigger group is replaced, is it possible to keep the current safety lever, as it appears more the era it was manufactured? If not that's alright also.

Thanks for your good customer service and great products,

David B. Wartelsky *Dave*
680 Tranquil Trail
Grand Junction, Colorado 81507

Home # 970 245-0214

*could not duplicate concern.
replace TPA, clean & test Rine
under BLP Con # 20. +*

Q note

Serial
Number

222781

Model: 700



RE00255018





