

Remington Arms Co., Inc.
Product Service
Legal Case #:7205

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
252518	1/4/2012	1/5/2012	1/24/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	High Caliber Guns & Ammo			2010 10th Ave	Parkersburg	WV	26101		
Incident		Adrian	Wells	3610 Sutton Place	Parkersburg	WV	26104		H 304-483-2486

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD shot hole in roof	Cause:4038 Could Not Duplicate Concern		Unknown	
S went off when unloading	Concern:1020 Fired on Bolt Opening			
C				

per cust letter: Gun has gone off or shot twice while unloading. In 85 it shot through my new truck roof while I was getting out of the wind and 10 degree to unload it. This years first day of deer season it fired as I unloaded it after hunting. I was very lucky no one was hurt.

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl	DOM
Remington	CF/BA	700/3006 SPRG	20000	179110	RM	11/1/1965
Date Purchased	Where Purchased	Accessories	Original Owner			
		TWO PIECE BASE	U			

CONCERN:SHOT TWICE WHILE UNLOADING SHOT THRU TRUCK ROOF

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Repair no charge as goodwill gesture						
	Repair/Replacement Cost	Repair/Replacement Date				
	67.40	1/24/2012				

1/24/12 Will repair no charge as goodwill. He bought it 2nd hand and has had some property damage in the past. I will send an owner's manual so that he has proper maintenance instruction to prevent the rust and stickiness in the future.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/5/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		RM
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

<http://cns03an13:2000/nsaann/PrintDisplay.aspx?ID=7205&Type=Case>

1/24/2012

	Fired while Obstructed		
	Muzzle/Crown Condition	Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Worn; Functioning	
	Stock Condition	Worn; Functioning	SCRATCHES,MARS,DENTS, FINISH WEAR
	Fore End Condition	---Select---	
Receiver	Condition	Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.007
	Notch	Slightly Worn; Functioning	
	Trigger	Condition	Slightly Worn; Functioning
---Select---		2#	
True		SET SCREWS ALTERED	
Sub-Assembly	M/700 Bolt Lock		
Non-Remington Components	Description		TWO PIECE BASE

7205

22"
RM 11/65
2#
.007

Adrian Wells 304-483-2486
3610 Sutton Place
Parkersburg, WV. 26104

Repair This gun has went
off or shot twice while I
was unloading it

In 85 it shot thru my new
Trucks Roof while I was getting out
of the wind and 10° to unload it.

This years first day of Deer season
it fired as I unloaded it after hunting.
I was very lucky no one was hurt

Adrian Wells

serial # 179110

179110

Model: 700



RE00252518

1179112
Made 702
R0025251 B





