

Remington Arms Co., Inc.  
Product Service  
Legal Case #:8266

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
291206	12/3/2012	12/4/2012	12/4/2012				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Craig	Whitebread	516 Whitebread Ln	Sugarloaf	PA	18249		

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI PD S C	Cause:4006 Fired on safe release Concern:1007	Altered Adjustments or Components Fired on Safe Release	Unknown	

12/21/12 Per note on SR, consumer stated that the firearm fired while switching from safe to fire while loading the firearm.cm

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM REM EX	n/a	A6757704	CV	4/27/1979
Date Purchased	Where Purchased	Accessories	Original Owner			
	ECO SUP POTTSVILLE PA	SCOPE BASE	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	29.44	12/21/2012				

12/21/12 Trigger assm set screws altered. Trigger not returning properly. Replace TPA, clean, test at BLSM program price.cm

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/4/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO

Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 7MM REM EXP
	Date Code		CV
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	GLASS BEDDED
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.007
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING PROPERLY WILL FOLLOW DOWN
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE

# Service Request

Remington Service

PO Box 700

Madison, NC 27025-0700



Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

22'  
CUY/  
2.5'  
100'

8266

Service Request Number  
SR00035901

Serial Number / Description  
A6757704  
Model 700 Center Fire

Date of Request: 11/21/2012  
Date Printed: 11/21/2012

Customer:  
CRAIG D WHITEBREAD  
516 WHITEBREAD LANE  
SUGARLOAF, PA 18249 US

Destination:  
Arms Services  
14 Hoefler Ave  
Ilion, NY 13357 US

Email:

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

## Reason for Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

## Service Request Section

Consumer has stated that the firearm fired while switching from safe to fire while loading the firearm.

Qty  
Needed

Warranty

Price Disc Amount

Serial Number:  
A6757704

Model: 700



RE00291206

T.A. set screws altered  
trigger not rehook properly  
up. TPA, & GAXIT TEST  
Under BCP Ron 820 +

Q

RECEIVED  
DEC 05 2012

BY: \_\_\_\_\_

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub .00  
Est .00

Grand Total: \$.00







