Remington Arms Co., Inc. Product Service Legal Case #:7223

Case Information

RE# **Date Opened** 1/7/2012 252903

Date Opened(PS) 1/9/2012

Date Closed 1/9/2012

Incident Date

Pre Lit Lit Obsolete

Customer Information

Type Business First Name Last Name

Street

City State Zip Age Contact

Incident

Jeremiah Winkler

2711 West 4th St North Platte NE 69101

H 308-530-3138 E jjwinkler@charter.net

Incident Information

Claims

Codes

Repair Est.

Medical Treatment Medical Status

PΙ

PD

Altered Adjustments or Cause:4006

Components

Fired on safety release

Concern: 1007 Fired on Safe Release

Unknown

C

1/25/12 Per note with rifle, gun fires when taking off safe. Sending it for SMP.cm

Firearm Information

Mfg. Remington

Type CF/BA Model/Ga.

SKU

Serial Bbl. DOM

Date Purchased

Where Purchased

700/3006 SPRG Accessories

20000

6849012 AZ 3/1/1975

REM ARM CAM GALT ONT CANADA TWO PIECE BASE

Original Owner U

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Cash

Date Date APV APV

Per Ilion, replace TPA, clean, test fire at BLSM program price

Repair/Replacement Repair/Replacement

Cost

Date

30.40

1/25/2012

1/25/12 Per Ilion, trigger assm set screws altered. Trigger no returning properly. Replace TPA, clean, test fire at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
	Examiner	B.TRAVIS		
Examination	Exam Date		1/9/2012	
	Product Type		RF	
	Action Type		A	
Examination			A A	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7223&Type=Case

1/25/2012

		ŧ
		2

	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
	Description		22" 3006 SPRG
	Date Code]	AZ
	Bore Plugged	False]
	Bulged	False	Ī
Barrel	Fired	False	
	Fired while Obstructed		-
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning]
Bolt	Face	Slightly Worn; Functioning]
	Handle	Slightly Worn; Functioning]
	Stop	Slightly Worn; Functioning]
	Condition	Slightly Worn; Functioning]
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False]
	Block Condition	Select]
Locking	Lug Condition	Slightly Worn; Functioning]
	Notch Condition	Select]
	Exterior Condition	Slightly Worn; Not Functioning	
Overali	Stock Condition	Missing]
	Fore End Condition	Select]
Receiver	Condition	Slightly Worn; Functioning]
Receiver	Bulged	False	
	Description]	M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS]
	Lift	Select	.006
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
<u></u>	Condition	Slightly Worn; Not Functioning	DIRTY,TRIG NOT RETURNING WILL FOLLOW DOWN
Trigger	Pull	Select	2.5#
•	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

7257

AZS/X

Model Number:	Serial Number: 6849012 Date of Purchase: 1997		
Name: Jeremiah Winkler			
Address (no F 2711 West 4th St.	O Boxes):		
City: North Platte	State: NE	Zip: 69101	
Phone (Daytime): 308-530-3138	Fax:		
E-mail Address: jjwinkler@cha	rter.net	_	
Please describe y	our problem:		
Gun fires when taking off safe. Seno modification program.	ding it in for	safety	
T.A. set	SCREWS AT	tened.	
This Not	- returning TPA, cleans 3LP Ron &	properly	
Rybice	TPA, cleane	-Trest Rine	
unden ?	3 LP Ron 8	20.+shp	
-	Que	te	
422 chara	acters left		

contact the Repair Center for services mated repair time.

Model: 700

RE00252903

/E OR SPENT SHELLS IN YOUR (WITH THE FIREARM. THIS IS A 'OU FEEL YOU MUST SEND SPENT SEPARATE PACKAGE AND INCLUDE E), TELEPHONE AND MODEL AND F YOUR FIREARM.

your firearm before sending it.

:: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a

firearm box. (Note: Original boxes may not be returned.)
:: Remove all accessories from your firearm to prevent loss or damage.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss

during shipment, so you may elect to purchase insurance from your carrier.

	Print
1	

Reset 같. ()		ب الح د	اران دران دران دران دران دران دران دران	
JAN	1	ŝ	2012	

BY:....





