

Remington Arms Co., Inc.
Product Service
Legal Case #:7226

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
252876	1/7/2012	1/9/2012	1/9/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Mike	Wolf	14797 Brook Hill Dr	Chesterfield	MO	63017		E.thwolf@netzero.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015	Improper Maintenance		
S	Fired on bolt closing	Concern:1008	Fired on Bolt Closing	Unknown
C				

1/25/12 Per note with rifle, in the month of Nov 2011, while sighting in the rifle, the gun went off on 2 occasions while pushing the shell into the chamber. This has happened before.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	25773	B6626596	PF	6/1/1985
Date Purchased	Where Purchased	Accessories	Original Owner			
	FOLSOM OF FLORIDA INC. 33616		U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test fire at 1/2 normal cost						
	Repair/Replacement Cost	Repair/Replacement Date				

1/25/12 Per Ilion, trigger assm very dirty and sticky. Sear is sticking to side plates. Replace TPA, clean and test fire at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/9/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	

Barrel	Description		22" 3006 SPRG
	Date Code		PF
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BOLT STOP RELEASE BROKEN
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select--	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	--Select--	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	--Select--	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	--Select--	.011
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	VERY DIRTY & STICKY SEAR STICKS TO SIDE PLATES WILL FOLLOW DOWN
	Pull	--Select--	6.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

Parts and Repairs: P:800-243-9700 F:356-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number: SRD0007674
Serial Number / Description: B6626596
Model 700 RIFLE

Customer: MIKE WOLF
14797 BROOK HILL DRIVE
CHESTERFIELD, MO 63017 US

Email: THWOLF@NETZERO.COM

Destination: Arms Services
14 Hoeffer Ave
Ilion, NY 13357 US

Email:

-Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return
M240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section

T.A. very dirty + sticky. SEAR is
STICKING to side plates. Replace
TPA, clean + RESTORE AT 1/2 NORM
LOST Quote

Parts And Service Details

Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount
----------	------	-------------	---------------	----------	-------	------	--------

In the month of November 2011, while sighting in
my rifle, the gun went off on 2 occasions
while pushing the shell into the chamber.
This has happened before.

Please call or email if you have questions.


Thank you

B6626596

Model: 700



RE00252876



Sub Total: .00
Est Sales Tax: .00
Grand Total: \$.00

BY:



186626596
Model 700
RE00252876



