

Remington Arms Co., Inc.
Product Service
Legal Case #:8072

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
286019	10/18/2012	10/23/2012	10/23/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Jessie	Wray Jr	7121 Milwaukee Ave	Wauwatosa	WI	53213		

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Fired when moving from safe to fire	Cause:4038 Concern:1007	Could Not Duplicate Concern Fired on Safe Release	Unknown
C				

11/5/12 Per note on SR, firearm went off while moving from safe to fire.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	26989	D6270642	KS	5/15/1998
Date Purchased	Where Purchased	Accessories	Original Owner			
	BILL HICKS & CO LTD		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, offer to replace TPA at 1/2 normal cost						
	Repair/Replacement Cost	Repair/Replacement Date				

11/5/12 Per Ilion, could not duplicate concern. Trigger assm dirty. To restore confidence in rifle, can offer to replace TPA at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		10/23/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE

Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		KS
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	MARS,DENTS
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,SOME RUSTING
	Pull	---Select---	4.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

frmREInquiry - Repair Inquiry

Repair Number: RE00286019

Serial: D6270642 Model 700 LH Center Fire Caliber:
3006 SPRG Produced: 05/15/1998 SKU: 26989

Repairman: Charles Swanson

Verify Repair

Status: Approval Hold 10/19/2012 12:31:51 PM

- ADDRESS INFORMATION

Customer

Received from

Return To

Received from

Name: JESSIE WRAY JR

JESSIE WRAY JR

Address 1: 7121 MILWAUKEE AVE

7121 MILWAUKEE AVE

Address 2: PO Box:

PO Box:

City: WAUWATOSA

WALWATOSA

State: WI Zip Code: 53213 Country: US

WI Zip Code: 53213 Country: US

FFL:					
------	--	--	--	--	--

01011900

Contact / Condition Problems Estimate History / Status Shipping / Billing

Problems Reported

Repair Notes

Repairman's Comments

Code	Desc
M580	NO INSTUCTIONS RECEIVED

Problems Found

Code	Desc
M993	ATTN= CSR

CSR Comments

Forward to product service for inspection. Firearm went off while moving from safe to fire. JJW 10/19/2012

Rennir Search

could not duplicate concern
TIA dirty, to restore confidence
in RIRLE can offer to replace TPA
at 1/2 normal cost. ①

Refresh


Close

Serial Number: D6270642

Model: 700

RECEIVED
(CI 25 20/2)

BY:



RE00286019





