

Remington Arms Co., Inc.
Product Service
Legal Case #:7863

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
277790	8/7/2012	8/20/2012	8/20/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Xtreme Outfitter	---	The Huntin Camp	2110 Sandy Lane	Laurel	MS	39443		W 601-649-6334

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern			
S	Fires on its own Concern:1025 Unexplained Discharge - No Mention of Safety Position		Unknown	
C				

Dealer sent rifle in w/note. Dealer stated gun fires on its own. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM REM MA	26933	T6208977	BP	1/13/1995

Date Purchased	Where Purchased	Accessories	Original Owner
	BIG BUCK TRADING POST	2 PC BASE W/RINGS	U

CONCERN: FIRES ON ITS OWN

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair @ a discount						

Repair/Replacement Cost	Repair/Replacement Date

8/22/12: Per Ilion - Could not duplicate concern. TA dirty & rusty. Replace TA, clean & test fire @ 1/2 normal cost - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		8/20/2012
	Product Type		RF
	Action Type		A
	Assigned To		T. NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 7MM REM MAG SS
	Date Code		BP
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select--	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	--Select--	
Magazine	Condition	---Select---	
	Box Condition	Missing	
Overall	Exterior Condition	Slightly Worn; Functioning	METAL RUSTY
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	--Select--	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	--Select--	.013"
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY AND RUSTY
	Pull	---Select---	4.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		2 PC BASE W/RINGS

INVOICE

X-TREME
OUTFITTER

2110 Sandy Lane • Laurel, Mississippi 39443
 601-649-6334

7863

24"
 BP1/95
 4.5#
 ,013

NAME Remington DATE 7-31-12
 ADDRESS _____ PHONE _____
 SALESPERSON _____ TERMS _____

CUSTOMER MAY CHOOSE LENGTH OF LAY-A-WAY

LAY-A-WAYS MUST BE PAID OUT IN: ☐ 30 DAYS ☐ 60 DAYS ☐ 90 DAYS

1. LAY-A-WAYS LEFT AT STORE MORE THAN ALLOWED TIME WILL BE RETURNED TO STOCK.
2. MINIMUM OF 25% MONTHLY PAYMENTS ARE REQUIRED TO KEEP ITEMS ON LAY-A-WAY.
3. A RETURN-TO-STOCK FEE OF 50% WILL BE CHARGED FOR ANY LAY-A-WAY NOT PAID OUT WITHIN TIME ALLOWANCE.

QUANTITY	ITEM	PRICE	AMOUNT
1	Rem 700 Tmag SN-T6208977		
	Fires on its own		
	Please Repair ASAP.		
	Thanks		
	Chute		

Number: T6208977

Model: 700



RE00277790

5 AND SAVE"

GES PRINTING INC. 601-649-3501

RECEIVED
 AUG 22 2012

BY: _____

could not duplicate concern
 T.A. dirty & rusty. replace TPA,
 clean + test AT 1/2 normal cost

Quote



UT62000977
700
NE00077700



