

Remington Arms Co., Inc.
Product Service
Legal Case #:8861

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
309191	4/26/2013	4/29/2013	4/29/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	AcuSport	---	AcuSport	One Hunter Place	Bellefontaine	OH	43311		W 800-543-3150 F 937-292-6268

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		Unknown
S FBC	Concern:1008	Fired on Bolt Closing		
C				

AcuSport sent a rifle into Ilion w/note: "Per cust uncocks itself or fires when you close the bolt 3 out of 5 times... credit only... RGA# 60091683". df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/300 WIN MA	85541	RR89082A	LH	2/6/2013 9:47:07 AM

Date Purchased	Where Purchased	Accessories	Original Owner
	ACUSPORT (OH) CORPORATION		U

CONCERN: UNCOCKS ITSELF OR FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Gun forwarded to Derek Watkins in E-town for exam						

Repair/Replacement Cost	Repair/Replacement Date

4/30/13: Gun forwarded to Derek Watkins in E-town for exam. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment

Examination	Examiner	B.TRAVIS	
	Exam Date	4/29/2013	
	Product Type	RF	
	Action Type	A	
	Assigned To	S.NICHOLS	
Cause	4038	Could Not Duplicate Concern	SENDING TO E-TOWN FOR EXAMINATION
Barrel	Description	26" 300 WIN MAG 5-R CERACOTE	
	Date Code	LH	
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Like new; Functioning	
Bolt	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
	Face	Like new; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
Extractor	Condition	Like new; Functioning	
	Cut Condition	Like new; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Like new; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Like new; Functioning	
	Stock Condition	Like new; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Like new; Functioning	
	Bulged	False	
Safety	Description	XMP SAFETY	
	Function	Like new; Functioning	
Sear	Lift	---Select---	.010
	Notch	Like new; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	2.75#
	Altered	False	FACTORY SEALANT PRESANT
	Sub-Assembly	X-Mark Pro	

AcuSport®

AcuSport Corporation • One Hunter Place • Bellefontaine, Ohio 43111-3001 • 800.543.3150 • FAX 937.292.6268

RC# 60091683
#1212

261
LAZ/1
2.75
01C

MANUFACTURER

MANUFACTURER NAME

Remington

CITY

RETURN OF DEFECTIVE MERCHANDISE

P.O. / Packing Slip No.

202756

MANUFACTURER NO.

25316

PRODUCT INFORMATION

ACUSPORT ITEM NO.	QTY	SERIAL NO.	PRODUCT DESCRIPTION & DEFECT	UNIT VALUE	TOTAL VALUE
85541	1	RR89082A	REM 700 TAC		894.04
			320WM 26 FLTD		
			XMP		

IMPORTANT- Please reference the number in the upper right corner on all correspondence, including your return packing list. Thank You!

TOTAL

per cust uncocks itself or fires when
you close the bolt 3 or 5 times

Credit Only!!

RECEIVED
APR 30 2013

BY: _____

FOR OFFICE USE ONLY

MANIFEST

120311779873973

WEIGHT

13.16389.52

DATE

4/24/13

Debit Memo

REASON FOR RETURN

DEFECTIVE MERCHANDISE RETURN



MERCHANDISE SHIPPED IN ERROR



ON PURCHASE ORDER NO.

Serial Number:

RR89082A

Model: 700



RE00309191

White Copy - Manufacturer Copy • Yellow Copy - Returns Copy • Pink Copy - Accounts Payable Copy









