

Remington Arms Co., Inc.

Product Service

Legal Case #:9693

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
331044	12/16/2013	12/17/2013	12/17/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Fred	Barnes	27189 Hwy 421	Hyden	KY	41749		H 606-672-2000 E fbshop@yahoo.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		Unknown
S FBC	Concern:1008	Fired on Bolt Closing		
C				

Per letter from Fred Barnes, "the gun fired when closing bolt one time without pulling trigger." jbi

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	84515	S6723366	CE	4/21/2010 1:45:08 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	HICKS INC		U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace trigger, check over and test fire at no charge						

Repair/Replacement Cost	Repair/Replacement Date
\$65	

12/19/13: Per Ilion, could not duplicate concern. To restore confidence in rifle, will replace trigger assembly, check over, test and target at no charge. jbi

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS

Examination	Exam Date	12/17/2013	
	Product Type	RF	
	Action Type	A	
	Assigned To	S.NICHOLS	
Cause	4038	Could Not Duplicate Concern	
Barrel	Description	24" 3006 SPRG XCR	
	Date Code	CE	
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description	XMP SAFETY	
	Function	Like new; Functioning	
Sear	Lift	---Select---	.011
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	3.5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	X-Mark Pro	

.24"
CE4/1
3.5
.01

Invoice

PO Box 550804
Houston, TX 77255



Date Purchased: 01/22/2013

BILL TO:

Fred Barnes
PO Box 870
Hyden, Kentucky 41749
United States

606-672-2000

fbshop@yahoo.com

Payment Method: Credit Card

SHIP TO:

Fred Barnes
PO Box 870
Hyden, Kentucky 41749
United States

could not disp. concern.
to restore confidence in
rifle will rep. T.A. & check
over, TEST + TARGET AT MK
Good - will #260 974

Products

Products	Model	Tax	Price (ex)	Price (inc)	Total (ex)	Total (inc)
1 x Remington Model 700 XCR II Bone Collector Rifle 84515, 30-06 Spr	84515	0%	\$886.91	\$886.91	\$886.91	\$886.91

Sub-Total: \$886.91

Flat Rate - \$9.99 First Gun, \$5.99 Per Additional Item (Flat Rate): \$9.99

Total: \$896.90

To Whom it may concern
Here is copy of Receipt

RECEIVED
DEC 19 2013

BY:

This Gun The Bolt is hard to
close when Gun is loaded. The
Gun fired ~~on the~~ when closing
Bolt one time without pulling Trigger
Also I fired the Gun a few times
on a Bench Rest it seem to Bounce At 100y
Around alot on Target Didn't shoot
like I thought it should have. I would
like you to Test fire Gun

Thank Fred

<https://mail-attachment.googleusercontent.com/attachment/?ui=2&ik=6a6563dff7&view=a...> 12/9/2013







