

Remington Arms Co., Inc.
Product Service
Legal Case #:9249

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
322575	9/30/2013	10/1/2013	10/1/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Lodge	Bliznesky	1220 S. Perry St.	Titusville	PA	16354		H 814-657-2721 E bliznesky@verizon.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006	Altered Adjustments or Components		Unknown
S	FSR	Concern:1007	Fired on Safe Release	
C				

Service Request # 33604 - Customer wrote a note on paperwork: "Fires when safety is moved from safe position to fire not touching trigger". df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/300 WIN MA	27037	RMEF7233	RA	11/6/2006 4:04:58 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	DAVIDSON S DSC INCORPORAT		U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
			Remington/700/CF/BA			
Per Ilion - Quote to repair						
	Repair/Replacement Cost	Repair/Replacement Date				

10/3/13: Per Ilion - TA pull screw altered. Trigger not returning properly. Replace TA, check over & test at 1/2 normal cost. Customer's wife, Kim, approved & paid for the repair by credit card. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment

Examination	Examiner	B.TRAVIS	
	Exam Date	10/1/2013	
	Product Type	RF	
	Action Type	A	
	Assigned To	S.NICHOLS	
Cause	4006	Altered Adjustments or Components	
Barrel	Description	26" 300 WIN MAG SS	
	Date Code	RA	
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description	XMP SAFETY	
	Function	Like new; Functioning	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING PROPERLY
	Pull	---Select---	1.5#
	Altered	True	PULL SCREW ALTERED
	Sub-Assembly	X-Mark Pro	

Service Request

Remington Service

PO Box 700

Madison, NC 27025-0700

www.Remington.com

Parts and Repairs: P.800.243.9700 F.336.543.7801

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **PLEASE RETAIN THIS COPY FOR YOUR RECORDS.**

Service Request Number SR00033604	Serial Number / Description RMEF7233 Model 700 RIFLE Caliber: 300	Date of Request: 11/01/2012 Date Printed: 09/24/2013																
Customer: LODGE BLIZNESKY 1220 SOUTH PERRY ST TITUSVILLE, PA 16354 US Email: bliznesky@verizon.net	Destination: Arms Services 14 Hoefler Ave Elion, NY 13357 US Email:																	
Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.																		
Reason For Return N1530 - CHECK TRIGGER SAFETY BLOCK		RECEIVED OCT 03 2013 BY: _____																
Service Request Section CONSUMER STATES THAT RIFLE FIRES WHEN BOLT CLOSES... ARS SENT VIA EMAIL																		
<table border="1"> <thead> <tr> <th>Material</th> <th>Type</th> <th>Description</th> <th>Qty. Needed</th> <th>Warranty</th> <th>Price</th> <th>Disc</th> <th>Amount</th> </tr> </thead> <tbody> <tr> <td colspan="8"> Fires when safety is moved from safe position to fire not touching trigger </td> </tr> </tbody> </table>			Material	Type	Description	Qty. Needed	Warranty	Price	Disc	Amount	Fires when safety is moved from safe position to fire not touching trigger							
Material	Type	Description	Qty. Needed	Warranty	Price	Disc	Amount											
Fires when safety is moved from safe position to fire not touching trigger																		
Serial Number: RMEF7233 Model: 700 		T.A. pull screw altered. Trig not return properly. Up. TA, check over + test AT. 1/2 ACorns (lost). Sub Total: .00 Est Sales Tax: .00 Grand Total: \$.00																

RE00322575

When you take safety off
the gun fire.

26"
RA 11/06
1.54
012







