

Remington Arms Co., Inc.
Product Service
Legal Case #:8689

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
303290	3/8/2013	3/11/2013	3/11/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Reno Sparks Scheels	Helen Clement	Reno Sparks Sch	1200 Scheels Dr	Sparks	NV	89434		W 775-331-2700 x 2266

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Slam fires	Concern:1008 Fired on Bolt Closing	Unknown	
C				

3/15/13 Per note with rifle, slam fires approximately every 20 rounds.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM REM MA	27097	G7174373	CG	4/12/2012 10:00:24 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	SHEELS - RENO SPARKS	TWO PIECE BASE	U			

CONCERN: SLAM FIRES

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, check over, test fire at no charge as a gesture of goodwill.						
	Repair/Replacement Cost	Repair/Replacement Date				
	48.04	3/15/2013				

3/15/13 Per Ilion, could not duplicate concern. To restore confidence in rifle will replace TPA, check over, test fire at no charge as a gesture of goodwill.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		3/11/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	SECOND TIME IN FOR REPAIR, FIRST TIME WAS FOR AN EXTRACTION ISSUE
Barrel	Description		26" 7MM REM MAG
	Date Code		CG
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Test Fired	False	
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	3.5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	X-Mark Pro	

REPAIRS

Insurance: \$

400.00

Date:

2-25-2013

To:

Remington Arms

14 Hoefer Avenue

Ilion, NY 13357

Serial Number:

G7174373

Model: 700



RE00303290

Manuf

Model

SN

Caliber

Reason

Remington 700ADL G7174373

7mm rem mag

Slam fires approximately every 20 rounds

CUSTOMER INFORMATION

Name:

Reno Sparks Scheels

Address:

1200 Scheels Drive

Sparks, NV 89434

ID:

FFL

Expiration:

3-1-2014

Signature:

[Signature]

Date:

2-25-2013

Phone:

Notes:

RECEIVED
MAR 13 2013

BY:.....

For any questions, please contact Helen Clement (775)331-2700 x2266

Reno Sparks Scheels

1200 Scheels Drive

Sparks, NV 89434

FFL 9-88-031-01-4C-01337

could not duplicate concern
to restore confidence in rifle
will replace TPA, check over
test fire at N/C Good will
best use.

#260974





