Remington Arms Co., Inc. Product Service Legal Case #:8551

Legal Case #:8551 Case Information RE# Date Opened(PS) Date Opened **Date Closed Incident Date** Pre Lit Lit Obsolete 298782 1/30/2013 1/31/2013 1/31/2013 Customer Information Zip Business First Name Last Name Street Contact State Age H 217-322-2847 3212 State St, Apt 5 Incident Ervin IL Doug Quincy 62301 E dervin03@hotmail.com Incident Information Claims Codes Repair Est. Medical Treatment Medical Status ΡI PD Cause: 4038 Could Not Duplicate Concern Unknown S Discharges when bolt is closed Concern:1008 Fired on Bolt Closing 2/4/13 Per note on SR, not happy with work on crown. Also, gun discharges when bolt is closed. It has happened twice.cm Firearm Information Mfg. Туре Model/Ga. SKU Serial Bbl. DOM Remington CF/BA 700/2506 REM 27009 G6832556 BE 1/21/2010 10:27:15 AM **Date Purchased** Where Purchased Accessories Original Owner WILLIAMS SHOOTERS SUPPLY U CONCERN:FBC Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/700/CF/BA Reim. Cash Cash Settlement Release of Claims Release Date Reimbursement Date Date Settlement APV APV To restore confidence, will replace TPA, recrown muzzle, check over and test no charge Repair/Replacement Repair/Replacement Cost Date 2/4/2013 145.20

2/4/13 Per Ilion, could not duplicate concern as received. To restore confidence in rifle, will replace TPA, recrown muzzle, check over and test no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		1/31/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	MUZZLE HAS A ROUGH CHAMFER CUT SECOND TIME IN FOR REPAIR
Barrel	Description		24" 2506 REM
	Date Code		BE
	Bore Plugged	False	
	Bulged	False	

	Fired	False	
	Fired while Obstructed		•
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	MAR ON MOUNT HOLE
Receiver	Bulged	False	
O C .	Description		XMP SAFETY
Safety	Function	Like new; Functioning	
Sear	Lift	Select	.010
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	Select	5#
	Altered	Тпие	PULL SCREW TURNED IN EXCESSIVE, SEALANT MISSI
	Sub-Assembly	X-Mark Pro	

Sim.	Repair Main E	FGI Repair		nar u Zaza				Hall Hall		观和特别	MAISTERN ST	
File	Add Repair	'Estimati	Repair	Expedite Repair	Inquiry	Repair Tools	CSR Tools	Reports	Table Maintenance	1 11 11		
	E f	rmREInqui	ry - Repa	ir Inquiry	a and the state of	idio na literate estable en con	o mane madera	ektoromen er in er in	enter militario de la Colombia.			
		pair Number:	1 <del> </del>	-06 REI	36832556 M M Produced:	lodel 700 Center Fi 01/21/2010 Repair C	re Caliber: 25 CNT: 2 SKU:	Repairman:	}		•	
		erify Repair DDRESS INF		Priority		8	551	Status:	New 1/25/2013 9:12:46	AM 		
		DDRESS INF	Custome			© Received from	Return To			eived from		
		Name:	DOUG EF	RVIN			DOUG ERV	/IN				24.
		Address 1:	3212 STA	TE ST APT 5	, <u>, , , , , , , , , , , , , , , , , , </u>	The state of the s	3212 STAT	ESTAPT5				BEND
		Address 2:		<u></u>	PO Box:			######################################	PO Box:			PIN/12
		City:	QUINCY				QUINCY		<u>na kara kara ana ana ana ana ana ana ana ana ana </u>	****	-'.	3th 5th
		State:	JIL Z	ip Code: 62301	Country:	us	IL Zip	Code: 62301	Country: US			.010
			**************************************	arten Aramania melitri miritik kalali adalahingan yang ang alli Mandalahan Amapa (a. 1913 ang ang		FFL:			. 101	D119D0	- '.	
i	C	entact / Cond	ition Probl	lems   Estimate   Histor	nv / Status	•	, , ,	, ,			CEI	
		-Contact Info	•		•	Received Condition			cessories Received		] [	
		Phone:	217 322 2	847	[]	Good	·	Co	(VII-VII-VIII-VIII VIII-VIII-VIII-VIII-V	Gty US	EB 0 ]	
		Fax:				Condition	handa a sa a mana han an an an an an	AD	With Stud	2		
		Email:	DERVINO	3@HOTMAIL.COM		Notes						
		Comments:	DEITTING	321101111111111111111111111111111111111		[						
	3 -4	Considerate.				CSR Consume Notes: work on	ernot happy with crown. Also gum					
			Çis.			discharge	es when bolt is	. 1133				
			I requ	Qualitatistiquis DPMM-Strictists estimatos		. 1	Consumer says it				.	
						could not de	At CRUCE	I'M ITTE	. U			
	1000	\ <del></del>	,			WILLIAM TPA	ATOST HE	muzzle	Refresh	C	lose	and the same of th
握し	6832	2556	<b>5</b>			Enfert Park	# 260	974				in sign
r Mo	del: 70	00								Pro T		
1111				RICE HERE HERE	100			3.54				
6					No.				The state of the s	الودوانين ومعالية بالماسري		ت بروه هر موسوسون و هو الموسون و موسون الموسون
							Granda		* e *		•	
1 188	PE	カクラ	927	782								
	1 × 1 V		/ 0 /	<b>5</b> 2		Theodorum Caso 🐔 20	LILASRPR 11	3 3 5 W.	Thursday, Jan 31	2013	3:38 4	AM

3:38 AM1

and a Travisby - ILN/Prod (1996) 12 CT (1996) 2 FrinkepairMain (1996)







