PrintDisplay Page 1 of 2

Remington Arms Co., Inc. Product Service Legal Case #:8478

Case Information RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 296162 1/11/2013 1/14/2013 1/14/2013 Customer Information **Business** First Name Last Name Street State Zip Age Type Contact 509 Douglas Hammond Police W 219-852-2917 Hammond Reporter Sgt Matthew Hammond IN 46320 St Dept Police E mjones@hammondpolice.com Incident Information Claims Codes Repair Est. Medical Treatment Medical Status ΡI PD Cause: 4038 Could Not Duplicate Concern Unknown S Fired when closing bolt Concern: 1008 Fired on Bolt Closing 1/17/13 Per note on SR, gun discharged while closing bolt. no damages, no injuries.cm Firearm Information Model/Ga. SKU Serial Bbl. DOM Mfg. Type Remington CF/BA 700/308 WIN 25709 G6802371 EC 10/1/2008 5:03:05 PM **Date Purchased** Where Purchased Accessories **Original Owner** JERRY S SPORT CENTER (WL) SCOPE BASE, BASE LEVEL U CONCERN: FBC Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/700/CF/BA Cash Cash Reim.

Settlement Release of Claims Release Date Reimbursement Cash Reim. Cash Settlement Date APV Date APV

Per Ilion, can offer to replace TPA, clean, test at 1/2 normal cost

Repair/Replacement Repair/Replacement Cost Date

1/17/13 Per Ilion, could not duplicate concern. Trigger assm set screw altered. Can offer to replace TPA, clean, test at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/14/2013
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 308 WIN HB
	Date Code		EC
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8478&Type=Case

ħ			<b>≓</b> !
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	CAMO PAINTED
Overall	Stock Condition	Slightly Worn; Functioning	CAMO PAINTED AND BEDDED
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
g_c_	Description		XMP SAFETY
Safety	Function	Like new; Functioning	
	Lift	Select	.011
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	DIRTY
	Pull	Select	2.5#
Trigger	Altered	True	SET SCREW ALTERED
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description		SCOPE BASE, BASE LEVEL

The STATE OF STATE OF THE STATE

Monday, Jan 14 2013

9:43 AM

RE00296162







