Remington Arms Co., Inc. **Product Service** Legal Case #:8563

Case Information

Date Opened(PS) RE# **Date Opened Date Closed Incident Date** Pre Lit Lit Obsolete 2/4/2013 299026 2/1/2013 2/4/2013

Customer Information

Type Business First Name Last Name Street State Zip Age Contact City W 972-724-2018 x 4080 Reporter Bass Pro Calida Weber Bass Pro 2501 Bass Pro Dr Grapevine TX 76051 E crweber@basspro.com 1017 Hampshire Ln Carrollton TX 75007 H 214-868-3180 Incident Lyn Harrison

Incident Information

Medical Medical Claims Codes Repair Est. Treatment Status ΡI PD Could Not Duplicate Cause:4038 Unknown

Concern Fired when moving safety to fire Concern: 1007 Fired on Safe Release

C

2/20/13 Per note with rifle, the customer lined up on a deer, looked down to move the safety from safe to fire and when he moved the safety the gun fired. His finger was not on the trigger. Trigger is too light, set @ 4 lbs or as one sees necessary.cm

Firearm Information

Serial Bbl. Mfg. Type Model/Ga. SKU DOM 8/24/2009 5:07:38 CF/BA 700/3006 SPRG

Remington Date

G6889241 WD 27017 Original

PM

Where Purchased Purchased

Accessories Owner

SCOPE, RINGS, TWO PIECE AMERICAN ROD & **GUN** 

BASE

U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Reim. Cash Cash Reimbursement Settlement Release of Claims Date Release Date Date Settlement APV APV

To restore confidence in rifle we will replace TPA, clean and test at no charge

> Repair/Replacement Repair/Replacement Cost Date

> > 46.04

2/20/2013

2/20/13 Per Ilion, could not duplicate concern. To restore confidence in rifle we will replace TPA, clean and test at no charge as goodwill.cm

Examination[Remington/CF/BA]

Part Sub-Part Code Comment PrintDisplay Page 2 of 2

Ì	Examiner	ļ	B.TRAVIS	
Examination	Exam Date	Ī	2/4/2013	
	Product Type	1	RF	
	Action Type	1	A	
	Assigned To	1	S.NICHOLS	
Cause	4038	Could Not Duplicate Concern		
Barrei	Description		24" 3006 SPRG	
	Date Code	]	WD	
	Bore Plugged	False		
	Bulged	False	]	
	Fired	False		
	Fired while Obstructed		_	
	Muzzle/Crown Condition	Slightly Worn; Functioning		
	Firing Pin	Slightly Worn; Functioning		
	Shroud	Slightly Worn; Functioning	1	
Bolt	Face	Slightly Worn; Functioning		
	Handle	Slightly Worn; Functioning	1	
	Stop	Slightly Worn; Functioning	Ī	
	Condition	Slightly Worn; Functioning		
Extractor	Cut Condition	Slightly Worn; Functioning		
	Ext/Eject Test	False		
Locking	Block Condition	Select		
	Lug Condition	Slightly Worn; Functioning	<b>1</b>	
	Notch Condition	Select	<del>-</del>	
	Exterior Condition	Slightly Worn; Functioning	<b>i</b>	
Overall	Stock Condition	Slightly Worn; Functioning	SCRATCHES	
	Fore End Condition	Select		
Receiver	Condition	Slightly Worn; Functioning	1	
	Bulged	False		
Safety	Description		XMP SAFETY	
	Function	Like new; Functioning		
Sear	Lift	Select	N/A	
	Notch	Slightly Worn; Functioning		
		Test Fired	False	
Feeding Test	Tests	False		
Trigger	Condition	Slightly Worn; Functioning	1	
	Puli	Select	3#	
	Altered	False	SEALANT PRESANT	
	Sub-Assembly	X-Mark Pro	1	
Non-Remington Components	Description		SCOPE, RINGS, TWO PIECE BASE	

24" WD8/00 3#

## **CUSTOMER FIREARM REPAIR**

MANUFACTURER	REMINGTON SERVICE 8563			
	ATTN: Arms Serv 14 Hoefler Avenu Ilion, NY 13357 (800) 243-9700			
FROM:	Bass Pro Outdoor Worl Attn: Calida Weber 2501 Bass Pro Drive Grapevine, TX 76051 (972) 724-2018 ext. 40 crweber@basspro.com		題G688924 Model: 700 RE00	41 
Serial Number:	G6889241			
Catalog No:	27017	_Model	Number: 700 CD	)L
Repair SKU:	1856475	_SKU:_	1026717	
ne moved the safe isted below with	nction: ed up on deer, looked do ty the gun fired. Finger any further questions. ger is to light please set	was not	on the trigger. Pleas	se contact customer
STATUS:				
CUSTOMER:	Lyn Harrison 1017 Hampshire Lane Carrollton, TX 75007 (214)868-3180	  	could not de to restouce con pith will hype Test AT 14/0	ifidence in the toph cleart
DATE SHIPPED:_	01/28/2013			
DATE RETURNEI	):		ECEIVE) Feb 0 5 2013	€£760914
			2 4.	





