Remington Arms Co., Inc. **Product Service** Legal Case #:9659

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed** Incident Date Pre Lit Lit Obsolete 330323 12/10/2013 12/11/2013 12/11/2013

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact 630 Westwood Dr Onalaska WI 54650 H 608-783-3846 Incident Ron Lund

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PI

PD Cause:4038 Could Not Duplicate Concern

Concern: 1007 Fired on Safe Release

Unknown

S6705715 WI 8/20/2009 8:57:27 PM

S FSR C

Per SR00069223, "discharge recently by simply switching safety off." jbi

Firearm Information

DOM Mfg. Type Model/Ga. SKU Serial Bbl.

CF/BA 700/300 WSM 27255 Remington **Date Purchased**

Where Purchased Accessories Original Owner

SPORTS SOUTH LLC

U

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Reim. Reimbursement Settlement Cash Release of Claims Date Settlement Release Date Date APV

Per Ilion, replace trigger, check over and test fire at no charge

Repair/Replacement Repair/Replacement

Cost

Date

\$50

12/12/13: Per Ilion, "could not duplicate concern. To restore confidence in rifle will replace trigger assembly, check over and test fire at no charge." jbi

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS

http://cps03sp01.remington.com:99/Remington PSA/PrintDisplay.aspx?ID=9659&Type=C... 1/2/2014

	Exam Date		12/11/2013
Examination	Product Type		RF
	Action Type		Α
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 300 WSM SS
	Date Code		WI
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	.011
	Notch	Slightly Worn; Functioning	
	Т	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	Select	3#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	X-Mark Pro	

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

WI8/

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

3 # ,01

Service Request Number

Serial Number / Description

SR00069223

S6705715

Model 700S RIFLE Caliber: 300

Customer: RON LUND

Email:

630 WESTWOOD DRIVE

ONALASKA, WI 54650 US

Date of Request:

11/27/2013

Printed:

11/27/2013

Destination:

Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section

Consumer states the firearm went off while moving the safety to fire



Qty Needed

Warranty

Disc Amount Price

could not depresent. To restore confidence in rifle WILL T.A. Checkover 4 Trest AT N/C

discharged once while unloading /flicking Safety on /off.

22013 - discharge recently by Simply Switching

- Grand + stal of Fifteen (15) shells fired

+ though Rifel.

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

.00

Est Sales Tax:

.00

Grand Total:

\$.00









