PrintDisplay Page 1 of 2

Remington Arms Co., Inc. Product Service Legal Case #:8999

Legal Case #:8999 Case Information Date Opened RE# Date Opened(PS) **Incident Date** Date Closed Pre Lit Lit Obsolete 6/18/2013 6/19/2013 6/21/2013 313751 Customer Information Business First Name Last Name State Zip Age Type Street City Contact NEW W 203-373-8542 ATTN: 174 SOUTH **NEW CAANAN** NEW CT 06840 CAANAN Reporter MARC E POLICE DEPT AVE **CAANAN** DEFE POLI marc.defelice@newcanaanct.gov Incident Information Claims Codes Repair Est. Medical Treatment **Medical Status** ΡI PD Cause: 4038 Could Not Duplicate Concern Unknown S Possible FSR Concern: 1007 Fired on Safe Release Service Request# 54836 - Service Request Section: Possible fire when safety released issue. df Firearm Information Model/Ga. Mfg. SKU Serial Bbl. DOM Type Remington CF/BA 700/7.62 NATO 86447 RR05287B BH 2/14/2013 9:39:56 AM **Date Purchased** Where Purchased Accessories Original Owner NEW CANAAN POLICE DEPARTMENT U CONCERN: POSSIBLE FSR Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/700/CF/BA Reim. Cash Cash Settlement Release of Claims Reimbursement Release Date Date Date Settlement APV APV Replace TA, clean & test to restore confidence in rifle at no charge goodwill gesture Repair/Replacement Repair/Replacement Cost Date \$50 6/21/13: I emailed Ilion to Replace TA, clean & test to restore confidence in rifle at no charge - goodwill gesture. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/19/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 7.62 NATO HB
	Date Code		ВН
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Like new; Functioning	
Bolt	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
	Face	Like new; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
Extractor	Condition	Like new; Functioning	
	Cut Condition	Like new; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Manamina	Condition	Select	
Magazine	Box Condition	Missing	
Overall	Exterior Condition	Like new; Functioning	
	Stock Condition	Like new; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Like new; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	N/A
	Notch	Like new; Functioning	
	T	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Like new; Functioning	
	Pull	Select	3.5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	X-Mark Pro	

## Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Marrice Request Number SR00054836

Serial Number / Description

RR05287B

Model 700 Center Fire

NEW CAANAN POLICE DEPARTMENT

ATTN: MARC DEFELICE

174 SOUTH AVE .

NEW CAANAN, CT 06840 US.

Email: Marc.Defelice@newcanaanct.gov

Date of Request:

06/12/2013

Date Printed: 06/12/2013

Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:

-Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M310 - PERFORM SAFETY CHECKS ON TRIGGER ASSEMBLY

Service Request Section

Possible fire when safety released issue

Parts And Service Details Material

Type

Description

Qrv Needed

Warranty

Price Disc Amount

BRR05287B



BY:\_\_\_\_

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total:

.00

Est Sales Tax:

.00

Grand Total:

\$.00







