Page 1 of 2 PrintDisplay

> Remington Arms Co., Inc. Product Service Legal Case #:7327

Case Information

Date Opened(PS) Incident Date RE# Date Opened Date Closed Pre Lit Lit Obsolete 5/22/2013 257731 2/7/2012 1/26/2012

Customer Information

State Zip Age Type Business First Name Last Name Street City Contact H 801-301-5136 Pedersen 11232 N. Shoreline Dr Highland UT 84003 W 801-579-6515 Incident Trent E trent.pedersen@ic.fbi.gov

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ы

PD Cause: 4006 Altered Adjustments or Components

S Fired on safety release

Concern:1007 Fired on Safe Release

Unknown

1/26/12 Per call from Pedersen, he is the original owner of this rifle and has had it glass bedded but no other alterations. He has shot about 200-300 rounds through it with no problems until recently. He had it at the bench and when he released the safety it fired.cm

Firearm Information Mfg. Type Model/Ga. SKU Serial Bbl. DOM CF/BA 700/260 REM 84018 S6653059 KC 5/14/2008 5:14:20 PM Remington **Date Purchased** Where Purchased **Original Owner** Accessories **GALLENSONS & ASSOCIATES I** 6/8/2008 Y CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Cash Reim. Release of Claims Settlement Release Date Reimbursement Date Settlement Date APV APV

Sending new TPA no charge as goodwill

Repair/Replacement Cost Repair/Replacement Date

1/26/12 Emailing ARS.cm 2/14/12 Per Ilion, trigger screws altered. Trigger pull set below specs and trigger not returning properly. Can offer to replace TPA, check over, test at 1/2 normal cost.cm 2/23/12 Per Pedersen, return as rec'd since we will not warranty the out of spec trigger that he had adjusted.cm 4/4/13 Per email from D. Watkins, "Mr. Pedersen has experienced a problem with his M700 fire control, see below. Please contact Mr. Pederson and make arrangements to have the fire control sent to E-town for my inspection." Mailing ARS for trigger to ship to Watkins. Called Pedersen and left a voice msgc. 801-579-6515, to let him know it would be mailed and that Watkins would contact him after inspection.cm 5/9/13 Per request from D. Watkins, I called Pedersen to let him know Watkins would be calling him tomorrow regarding the inspection cm 5/21/13 Per D. Wakins, send new TPA no charge as goodwill to replace the one Pedersen sent Watkins, ord #1505399.cm

Examination[Remington/CF/BA]

Sub-Part	Code	Comment	
Examiner		B.TRAVIS 2/8/2012	
Exam Date			
Product Type		RF	
Action Type		A	
Assigned To		T.NAGLE	
4006	Altered Adjustments or Components		
	Examiner Exam Date Product Type Action Type Assigned To	Examiner  Exam Date  Product Type  Action Type  Assigned To  Altered Adjustments or	Examiner   B.TRAVIS

PrintDisplay Page 2 of 2

1	Description		24" 260 REM FL SS
	Date Code		KC
	Bore Plugged	False	
Barrel	Bulged	False	
Barrer	Fired	False	
	Fired while Obstructed		_
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	]
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	BEDDED
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Received	Bulged	False	
	Description		XMP SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.009
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING PROPERLY WILL FOLLOW DOWN
Trigger	Pull	Select	1.5#
	Altered	True	SCREWS ALTERED
	Sub-Assembly	X-Mark Pro	

#### Mitchell, Christy

From:

Pedersen, Trent E. [Trent.Pedersen@ic.fbi.gov] Tuesday, May 21, 2013 9:46 AM Mitchell, Christy

Sent:

To:

Kristy,

Sorry for the delay in getting back to you but I have been a bit overwhelmed the past few days. Attached is my mailing address:

Trent Pedersen

C/O FBI

5425 W. Amelia Earhart Drive, Salt Lake City, Utah 84116. The telephone number for the office is 801-579-1400.

Thanks

Trent



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

### ARS LABEL REQUEST FORM

DATE:		4/4/2013	REQUESTED BY:	christy	
QUANTITY:	1		WEIGHT PER PACK	AG .	2 lbs
PLEASE CHECK ONE: MEDIA COORDINATOR TO MAIL			I WILL MAIL	xxxxxxxxxx	×××××××
DESCRIPTION:	trigger				

#### LABEL INFORMATION

MAIL LABEL TO:	Trent Pedersen	
	11232 N. Shoreline Dr	
	Highland, UT 84003	
RETURN ITEM TO	): Remington R&D	
	Attn: Derek Watkins, case # 7327	
	E'town, KY	

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX596 APR 4, 2013 ALL CURR USD 1 OF 1 SVC GNDCOM ACT WT 2.0 LBS TRACKING# 1Z4XX5969067190833 REF 1:TRENT PEDERSEN/SWP/CHRISTY REF 2:TRIGGER

HANDLING CHARGE 0.00

SINGLE-PIECE PUB RATE CHRGS: SYC T/P USD
DV 0.00 COD 0.00 RS 0.50

DC 0.00 DGD 0.00 SD 0.00

AH 0.00 PR 0.00 SP 0.00

TOT PUB CHG 11.12 PUB+HANDLING 11.12

federsen shipped 4/12 sched. deliv. 4/17

#### Mitchell, Christy

From: Watkins, Derek L.

**Sent:** Thursday, April 04, 2013 1:44 PM

To: Mitchell, Christy
Cc: Moore, Tony L.

Subject: FW: Slap Fire trigger on Remington 700 CDL SF Ltd Edition 260 Rem.

#### Christy,

Mr. Pedersen has experienced a problem with his M700 fire control, see below. Please contact Mr. Pederson and make arrangements to have the fire control sent to E-town for my inspection. His phone number is 801-579-6515.

From: Moore, Tony L.

Sent: Thursday, April 04, 2013 1:35 PM

To: Watkins, Derek L.

Subject: FW: Slap Fire trigger on Remington 700 CDL SF Ltd Edition 260 Rem.

Who can we have to reach out to Trent and get the trigger back? Can you contact him, info is below? Thanks

From: TRENT E PEDERSEN [mailto:trentpedersen1@msn.com]

Sent: Sunday, March 24, 2013 3:48 PM

To: Moore, Tony L.

Subject: RE: Slap Fire trigger on Remington 700 CDL SF Ltd Edition 260 Rem.

Tony, I was pretty much out of commission this past week with a new baby and trying to get things settled at home so I apologize for not getting back with you. I will be back to work this week and I am more than willing to send the trigger back to you so you can take a look at it if you will give me the information on where to send the parts. I replaced it with a Timney as I didn't feel the trigger was safe based on the slap firing. After Remington initially refused to address the trigger issue we adjusted the trigger pull (per Remington's instructions for this trigger) and even at high lbs....5-8 lbs it was still slam firing so thus, I took it off and replaced it with the Timney. Not that it is my job to tell you how to run your company.....and I am very familiar with the prior law suits re: triggers, etc. but myself, my gunsmiths and everyone I know that is serious about shooting much preferred the old Remington style triggers that were very easily adjusted and I never had an issue with the old style triggers having had them adjusted by my smiths down to 2-3 lbs.

I will likely be able to be reached at 801-579-6515 most of this week.

#### Thanks

#### Trent

On Mar 15, 2013, at 11:45 PM, "TRENT E PEDERSEN" < <a href="mailto:trentpedersen1@msn.com">trentpedersen1@msn.com</a> wrote: Tony, you reached out to me and requested my information. Here is my info. that I provided with the rifle when I previously sent it back to Remington...Trent Pedersen, 11232 N. Shoreline Dr. Highland UT, 84003. The rifle was a .260 Rem, CDL SF Ltd Edition. The best way to get a hold of me is this email address or my work email address <a href="mailto:trent.pedersen@ic.fbi.gov">trent.pedersen@ic.fbi.gov</a> or my phone 801-301-5136. I appreciate the fact that you are at least willing to look into this. Because the trigger was not safe I replaced it with a Timney which is currently on the rifle but I believe I still have the old trigger mechanism in the gun safe. I have built a couple of custom rifles ... 6.5-284s on Rem 700 actions and frankly, I was a huge Remington fan and supporter until this incident but it really soured me on Remington when the first and only time I had an issue in 30+ years and I was sent packing. Trent

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700

ATTN: Prod Serv #7327

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number

Serial Number / Description

SR00010966

S6653059

Model 700 RIFLE

Customer:

TRENT PEDERSEN 11232 N. SHORELINE DR HIGHLAND, UT 84003 US

Email: trent.pederssen@ic.fbi.gov

14 Hoefler Ave Ilion, NY 13357 US

Destination:

Arms Services

trent pedersen lic. Sbigor Email: trent pedersen 1@msn.com

Date of Request:

Date Printed: 01/26/2012

01/26/2012

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

DEFECTIVE SAFETY, GUNFIVED multiple times M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

when safety was moved From SAFE TO FIRE.

Description

Service Request Section

Parts And Service Details Type

Material

Qty Needed

Price Disc Amount

最56653059

Trig. screws a Hered. Trig,
pull set below i pecs and
Trig. Not returning properly,
can often to replace TDA, check
over + tos + A+ 1/2 Mormal cost.

Quote

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

.00

Est Sales Tax:

MOTE: Please complete and print this form, and then include it with your firearm.

Model Number: Rem 700 SF CDL LTD	Serial Number: \$665	3059	
Are you the original owner?: X YES NO			
Name: TRENT PEOERSEN O	Date of Purchase: 6/8	12008 \$255	(see receipt)
Address (no PO Boxes): 11232 N. SHore	LINE De.		
City: Highland	State: VT	Zip: 1003	
Phone (Daytime): 301-301-5136	Fax:		
E-mail Address:(if e-mail eddress is provided, notification	on of receipt and shipment will be	* * * · · · · · · · · · · · · · · · · ·	
sent) trentpedersen 1@ min, com	y 1000 11. 11. 11. 11. 11. 11. 11. 11. 11	•	
E-mail Address: + rent. pedersene ic.	fbi.gov		
Please describe your problem and date of occurrent			4
I was shorting the weapon from	n the bench chrono	g raphing loads	
Actor cleaning the weapon. & starte	d to fire a 3 shot i	string. I	
THOSE ROUNDS	FIRED WHEN THE	SAFRETY WAS	
11 - 0 == cc.ec 14:	t had cube cabe a contract of the contract of	100 TWI ON MINING	i) -
Occasions when I dry fired it itself. THE MESPERES WER	c watursen RY	CA DAN WARD,	1
ANFRE CNEPER FROM SALTER	KE CETY.		
I HAVE SHOT 100-200 rounds thro-	ah this rifle as curm	will SET UPWI	
No busou beoblems. Con es ans	ARE W/ C WILLT SAFE	ity/trigger mech	writm.
		<b>当</b>	
500 W cheracters left			
Ammunition Information:			
Manufacturer.	Type:		-
Office is a hullet welcould have about the governing		Transfer to the same products	ļ
Other (i.e. builtet weight/type, shot size, powder):			1
Handload Information:			
Powder Used: H4350	Powder Weight 449	· ·	1
Case/Hull Used: Ren	Primer Used: 210M		
Bullet Type/Shot Size: 120 N&T	Reloader Used: RCRS		
			•

2.82 COL . 020 - . 030 jump

nson's

00 SOUTH CITY, UTAH 328-2016

GALLENSONS 166 E. 200 SO SALT LAKE CITY UT 84111 (801) 328-2016 M#240020128585

C O P Y 06/09/2008 14:03:41 Sale:

Transaction #

Reference No.: 00000017 Auth.Code: 009889 Respon. APPROUED

CUSTOMER COPY

	*				÷.		18	399	2
		94 3 * , .:Î	(G)	Galle	N & A	SSOCI	A (ATES)	PHOI 01) 328	-2016
	<u>G</u> ,	<u>A</u> (		SOUTH .	S			<u> </u>	
4	SOID B Als)/a	ed .			REC'D		61	18/c	58
•	Cat.	Quan.		DESCRI	PTION		Price	Amo	ouni OC
		/	1	CA 1	00	20030		853	
			3/	4. SE	<i>333</i>	0	ا ح		
			É	18-12	850	5	.`		
		1	تركاني	Louis		20		137	
		1.		San 8 C	~ .	100		1/2	00
	<del></del>	1	-			25	.15	1534	145
		<del>                                     </del>					× ×	91	44
		├	-		•	1. 1	1	1426	39
í		<del> </del>	$\vdash$			-	1	7	32
		<del> </del>	┞-			01	10/	11.00	287
i			_		7	- = -		100	30
		6	13	574	- CO (T)	<b>5</b> {	100	100	2 3
			L					F75	
,	_							13	339
ć.	NO REFUND WITHOUT THIS SALES SLIP								

NO REFUND AFTER 30 DAYS

SPECIAL ORDER
NAME TRENT PEDERSEL (FEE)
ADDRESS 11232 N. Shoreline
cmy Highraud , UTAH
DATE 4
PHONE 801-579 -4716
MAKE REMINE ON PRICE BAS. 4 102
MAKE REMINE ON PRICE PRICE
P.O
DESCRIPTION 2 SHIPPING
# 840/8 / TOTAL
Chon-refundable DEPOSIT 100
BAILANTE
1) O John
1 0 VDI.
CUSTOMER SIGNATURE *

\* You must bring copy of special order to get credit for deposit.
Valid 2 years from date of order.

ORDERED FROM

DATE

SALESMAN

## Service Request

#### Remington Service PO Box 700

ATTN: Prod Serv #7327

Parts and Repairs: P:800-243-9700/F:336-548-7801

Madison, NC 27025-0700 www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number | Serial Number | Description Date of Request: 01/26/2012 SR00010966 S6653059 Date Printed: 01/26/2012 Model 700 RIFLE Customer: TRENT PEDERSEN Destination: Arms Services 11232 N. SHORELINE DR 14 Hoefler Ave HIGHLAND, UT 84003 US Ilion, NY 13357 US Email: trent.pederssen@ic.fbi.gov Email: Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed. Reason For Return M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION Service Request Section Parts And Service Details Material Type Description Qty Needed Warranty Price Disc Amount THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) .00 Sub Total: being sent based on the conversation with our representative. .00 Est Sales Tax:

## Service Request

#### Remington Service PO Box 700

Sub Total:

Est Sales Tax:

Madison, NC 27025-0700 ATTN: Prod Serv #7327

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

01/26/2012 Service Request Number | Serial Number | Description Date of Request: SR00010966 S6653059 Date Printed: 01/26/2012 Model 700 RIFLE Customer: TRENT PEDERSEN Destination: Arms Services 11232 N. SHORELINE DR 14 Hoefler Ave HIGHLAND, UT 84003 US Ilion, NY 13357 US Email: Email: trent.pederssen@ic.fbi.gov Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed. Reason For Return M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION Service Request Section Parts And Service Details Material Type Description Qty Warranty Price Disc Amount Needed

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s)

being sent based on the conversation with our representative.

.00

.00

Please send your firearm back via a traceable method of shipping to the address below.

This Service Request number is only valid for this return.

Please follow these guidelines:

- Include a copy of your proof of purchase to assist in the evaluation of your repair
- Record your serial number for future reference
- Remove <u>any</u> accessories (sling, scope, scope mounts, case, etc.) unless these items are needed to assist in the evaluation.
- Properly package your <u>unloaded</u> firearm. Do not ship in your hard case (note: Original boxes are not returned with repair)
- Do not send live/loaded or spent ammunition with your firearm.
- Please package the ammunition in a secure carton or box.
- The package should be stuffed to prevent movement.
- Include service request number.
- Shipment of live ammo must be via U.P.S. only.
- Please advise your local U.P.S. mailing center of the contents so that a special Other Regulated Materials-Domestic (ORM-D) label can be applied.

Please let us know of any address change requests by email or phone. Our returns process will take approximately 2-3 weeks to complete and a confirmation email will be sent once we have shipped your firearm.

Should you have any further questions or concerns please don't hesitate to contact us via email (<u>info@remington.com</u> <<<u>mailto:info@remington.com</u>>>) or by phone at 800-243-9700, M-F 9am - 5pm, EST. We look forward to helping you resolve this issue!

(cut here)	
Mailing Label:	
Mailing Laboli	

Arms Services SR# SR00010966 14 Hoefler Ave Ilion, NY 13357 US

Email:

Attn: Prod Serv #7327



## ARS LABEL REQUEST FORM

DATE:	01/26/2012	Service Request #	SR00010966
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	mitchelles	email address:	Christy.Mitchell@remington.com

Business:

Remington Service
PO Box 700
Madison, NC 27025-0700
www.Remington.com

## LABEL INFORMATION

MAIL LABEL TO:

TRENT PEDERSEN
11232 N. SHORELINE DR
HIGHLAND, UT 84003 US
SR00010966

Email trent.peders.en@ic.fbi.gov

RETURN ITEM TO:

ILN
Arms Services



4XX596 JAN 26, 2012 ACT WT 10.0 LBS #PK 1 SVC GNDCOM BL WT 10.0 LBS #PK 1 TRACKING# 124XX5969066419820 ALL CURRENCY USD REF 1:SR00010966 REF 2:

HANDLING CHARGE 0.00 FRT: 3RD

SHIPMENT PUB RATE CHARGES: SVC T/P USD

CV 0.00 COD 0.00 RS 1.00

DC 0.00 PR 0.00 ROD 10

TOT PUB CHG 14.02 PUB+HANDLING 14.02

ATTN: Prod Serv #7327

## ARS LABEL REQUEST FORM

DATE:	01/30/2012	Service Request #	SR00010966
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	mitchelles	email address:	Christy.Mitchell@remington.com

**Bùsiness:** Remington Service PO Box 700 Madison, NC 27025-0700

www.Remington.com

## LABEL INFORMATION

MAIL LABEL TO: TRENT PEDERSEN 11232 N. SHORELINE DR

HIGHLAND, UT 84003 US SR00010966

Email: trent.pedersen@ic.fbi.gov

**RETURN ITEM TO:** ILN

Arms Services


## 

4XX596 JAN 30, 2012 ACT WT 10.0 LBS #PK 1 SVC GNDC'OM BL WT 10.0 LBS TRACKING # 1Z4XX596C066796075 ALL CURRENCY US REF 1:SR 00010966 ALL CURRENCY USD


REF 2:

FRT: 3RD HANDILING CHARGE 0.00 SHIP'MENT PUB RATE CHARGES: SVC T/P USD FIS 1.00 COD 0.00 DV 0.00 DC 0.00 At 1 0.00 7.0T PUB CHG 14.02 DGD 0.00 ROD 0.00 PR 0.00 PUB+HANDLING 14.02

ATTN: Prod Serv #7327







## # Pitney Bowes



# ShipRequest™



Ship To:

Derek Watkins, Case 7327

Company:

Remington Arms, LLC

Address 1:

315 W. Ring Rd

Address 2:
Address 3:

City:

Elizabethtown

State/Province:

Kentucky

ZIP/Postal Code:

42701

Country:

United States

email:
Phone:

Account:

230145

Package Type:

Package

Address Type:

Commercial

Deliver By:

Fri, May 3, 2013

Package ID:

8800

Special Instructions:

Sender Name:

Christy Mitchell

email:

Christy.Mitchell@remington.com

Prepared By:

