

Remington Arms Co., Inc.

Product Service

Legal Case #:9145

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
319028	8/28/2013	8/29/2013	8/29/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident	Lawerance	Vixathep		1291 SW Napoleon Place	Troutdale	OR	97060		H 503-703-2393 E anop_vixathep@hotmail.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Unexplained Discharge - No Mention of Safety Position	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown
C				

Per SR00059057 Service Request Section, "Bolt hard to lock into battery. Also consumer had accidental discharge."

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/300 WSM	27333	G6944968	WF	8/28/2010 10:28:43 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	WHOLESALE SPORTS/SPORTSMA	MUZZLE BRAKE	U			

CONCERN: ACCIDENTAL DISCHARGE

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Repair as needed at no charge and test fire						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$50					

8/30/13: Per Ilion, "Could not duplicate concern of accidental discharge. Will replace T.A. to restore confidence in rifle. Repair as needed. Test fire." jbi

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/29/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 300 WSM
	Date Code		WF
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Slightly Worn; Functioning	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	3.5#
	Altered	False	INCONCLUSIVE
	Sub-Assembly	X-Mark Pro	

Non-Remington Components	Description	MUZZLE BRAKE
--------------------------	-------------	--------------

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System

Repair Inquiry - Repair Inquiry

Repair Number: RE00319028 Serial: G6944968 Model: 700 Name: Fire Caliber: 300 VGM Product: 00212210 S&U: 2203

Verify Repair: ☒ High Priority 9145 Reservant: James Gansley

Status: Estimating 8/27/2013 11:22:18 AM

ADDRESS INFORMATION

Customer: ☐ Received Item: ☐ Return To: ☐ Received Item

Name: LAWRENCE VIGATHET LAWRENCE VIGATHET

Address 1: 121 SW NAPOLEON PLACE 121 SW NAPOLEON PLACE

Address 2: PO Box

City: TROUTDALE TROUTDALE

State: OR Zip Code: 97060 Country: US OR Zip Code: 97060 Country: US

FFL: 9101190

Contact / Condition / Problem / Estimate / History / Status / Shipping / Billing

Contact Information

Phone: (503) 703 2293 Gmail

Fax: Condition

Email: Notes

Comments: Add Part back to the battery

CSR: New container had

Notes: accidental discharge

Accessories Received

Code: Qty

Qty: Qty

Repair Search Refresh Close

2411
WF8/11
3.5#
.012

Transw - BNPred fmilrepairMain -DMC88CH497L Thursday, Aug 29 2013 4:28 AM

Serial Number:

G6944968

Model: 700



RE00319028

RECEIVED
AUG 30 2013

BY:.....

could not duplicate concern
or accidental discharge. will
replace T.A. to restore
confidence in rifle. repair
as needed + test Rifle at
M/C.
warranty







