

Remington Arms Co., Inc.  
Product Service  
Legal Case #:8825

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
308507	4/19/2013	4/22/2013	4/22/2013				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident	Exeter Automotive	James	Smith	4965 Hafer Road	Reading	PA	19606		W 610-779-4944 C 484-256-1478

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006	Altered Adjustments or Components		
S	Gun went off when set down on butt stock	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown
C				

Customer sent a note w/gun: Mr. Smith stated "when I went to purchase the gun they set the gun down on the butt stock and the gun went off... Problem could not be duplicated". df

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	40X/308 WIN	87920	039702B	CE	4/14/2010 10:00:35 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	TOMMY GUN INC	SCOPE BASE,SOCK,HARD CASE	U			

CONCERN:WENT OFF SETTING IT DOWN ON BUTT

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Repair as needed at n/c						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$50					

4/23/13: Per Ilion - Check over completely & repair as needed at n/c. df

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/22/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4006	Altered Adjustments or Components	
Barrel	Description		18" 308 WIN HB
	Date Code		CE
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Not Functioning	FAILS NULL TEST
	Pull	---Select---	4.5#
	Altered	True	FACTORY SEALANT MISSING
	Sub-Assembly	M/700 Non-Bolt Lock	

Keith,

8825

18"  
4.5"  
.012  
CE 4/11

Enclosed is one Remington 40x Serial number 039702B. When I went to purchase the gun they set the gun down on the butt stock and the gun went off, good thing no rounds were in it. Problem could not be duplicated. The gun came back to you to have the scope mount installed and gone over before I bought it. I had some problem with the trigger one time it fired when I closed the bolt. I cleaned the trigger with lighter fluid and that has never happened again. I had a lot of problems with a delay when you pull the trigger, I adjusted it and made it better but it still does not feel right!!

I would like you to go over the whole gun, and any service you recommend be done. I had to take the muzzle break off to compete. Guys on the firing line were getting hit with the muzzle blast (baby's). I do run an AAC suppressor on it, that is why I put the flash hider on it.

If I would want the XM-3 McMillan stock, bipod, and sling installed on this gun is that something you would be able to do? Was the gun chambered for a specific type of 308 round or grain bullet?

Call me any with any questions, and for payment.

My shipping information is:

Exeter Automotive Inc.

c/o James Smith

4965 Hafer Road

Reading, PA 19606

Work- 610-779-4944

Cell - 484-256-1478

RECEIVED  
APR 23 2013

BY:.....

Thanks,

Jim

Serial  
Number:

039702B

Model: 40X



RE00308507

check over completely  
repair as needed A+ N/C

#260974









