PrintDisplay Page 1 of 2

Remington Arms Co., Inc.
Product Service
Legal Case #:9669

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 332496 1/2/2014 12/12/2013 1/14/2014

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Incident Jay Hancock 7611 South Westshore Blvd Tampa FL 33616 H 919-796-6228

Incident Information

Medical Medical Claims Codes Repair Est. Treatment Status cut thumb on safety Could Not Duplicate Cause:4038 PD Concern N S FSR Concern:1007 Fired on Safe Release

C

12/12/13: I received call from Jay Hancock, he said that he was deer hunting in November and the gun fired when he pushed the safety off. He said that the safety cut his thumb, but he did not receive any medical treatment. jbi

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM
Remington CF/BA SPT-78/3006 SPRG 26164 C6334245 BJ 1/6/1989

Date Purchased Where Purchased Accessories Original Owner

GLEN ZANDERS SPTG GDS N

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/SPT-78/CF/BA

Settlement Release of Claims Release Date Reimbursement Reimbursement Reimbursement Release Date Release Date Reimbursement Release Date Reimbursement Release Date Reimbursement Release Date Re

Replace TPA, check over and test at no charge

Repair/Replacement Repair/Replacement Cost Date

12/12/13: Sending ARS, letter, and SR paperwork. Box sent on SAP order 1575077. jbi 1/7/14: Per Ilion, could not duplicate concern. jbi 1/10/14: I emailed Ilion to replace trigger, check over, and test at no charge as a goodwill gesture. jbi

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment		

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9669&Type=... 1/14/2014

	Examiner		B.TRAVIS
Examination	Exam Date		1/3/2014
	Product Type		RF
	Action Type		Α
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
	Description		22" 3006 SPRG
	Date Code		BJ
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	ACTION VERY DIRTY UNDER STOCK
Overall	Stock Condition	Slightly Worn; Functioning	MARS,DENTS,SCRATCHES
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
G C .	Description		STANDARD SAFETY
Safety	Function	Like new; Functioning	
Sear	Lift	Select	.010
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	Select	4.5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Non-Bolt Lock	

Remington.

72" 351/8 4.5 01

COPY

December 11, 2013

Jay Hancock 7611 South Westshore Blvd Tampa, FL 33616 Phone: 919-796-6228 9669

Ref # 9669, Model SPT-78, Serial #C6334245

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination. A box will arrive separately.

Please include a copy of this letter and service request to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm.

I hope that this action will keep you a loyal Remington customer.

Sincerely, J.B. Irving Consumer Affairs Administrator Remington Arms Co, LLC / H&R Phone: 336-548-8684

Fax: 336-548-7872

C6334245

Model: 78-SPORTSMAN

RF00332496

DECEIVE JAN 07204 6 BY:

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number | Serial Number / Description Date of Request: 12/12/2013 SR00070890 C6334245 Printed: 12/12/2013 Model SPT-78 RIFLE Destination: Customer: JAY HANCOCK Arms Services 7611 SOUTH WESTSHORE BLVD 14 Hoefler Ave TAMPA, FL 33616 US Ilion, NY 13357 US Email: Email: Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed. Reason For Return M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION Service Request Section. Product Service #9669. jbi Parts And Service Details Description Qty Needed Warranty Disc Amount Material Type Price THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) Sub Total: .00 being sent based on the conversation with our representative. Est Sales Tax: .00

\$.00

Grand Total:

ARS LABEL REQUEST FORM

DATE:	12/12/2013	Service Request #	SR00070890	
QUANTITY:	l l	WEIGHT PER PACKAGE:	10 LBS	
REQUESTED BY:	irvingjb	email address:	I will mail	
Business:		Remington Service		
		PO Box 700 Madison, NC 27025-0700		

www.Remington.com

LAREL INFORMATION

LABEL INFORMATION			
MAIL LABEL TO:	JAY HANCOCK 7611 SOUTH WESTSHORE BLVD TAMPA, FL 33616 US SR00070890		
	Email:		
RETURN ITEM TO:	ILN		
	Arms Services		



4XX596 DEC 12, 2013 ALL CURR USD 1 OF 1 SVC GNDCOM ACT WT 10.0 LBS
TRACKING# 1Z4XX5969067195007
REF 1:SR00070890
REF 2:
HANDLING CHARGE 0.00 SVC T/P USD SINGLE — PIECE PUB RATE CHRGS: SVC T/P USD DV 0.00 COD 0.00 RS 0.50 DC 0.00 DGD 0.00 SD 0.00 AH 0.00 PR 0.00 SP 0.00 TOT PUB CHG 11.68 PUB+HANDLING 11.68

ATTN: Product Service









