

Remington Arms Co., Inc.
Product Service
Legal Case #:8915

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
310865	5/14/2013	5/15/2013	5/15/2013				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Blackland Gun Works		Blackland Gun W	12365 US 79	Taylor	TX	76574		E blacklandguns@eccwireless.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance			
S	Gun went off without pulling the trigger	Concern:1025 Unexplained Discharge - No Mention of Safety Position	Unknown	
C				
5/16/13 Per note on SR, gun went off, without pulling the trigger.cm				

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	600/308 WIN	n/a	72609	DN	9/1/1966
Date Purchased	Where Purchased	Accessories	Original Owner			
		SCOPE BASE	U			

CONCERN: WENT OFF WITHOUT PULLING TRIG

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/600/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean and test under recall at no charge						
	Repair/Replacement Cost	Repair/Replacement Date				
	43.86	5/16/2013				

5/16/13 Per Ilion, trigger assm dirty and sticky and rusty. Sear works sluggish. Replace TPA, clean and test under recall at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		5/15/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4015	Improper Maintenance	
Barrel	Description		18.5" 308 WIN
	Date Code		DN
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	RUSTY,DIRTY
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.004
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,STICKY,RUSTY.SEAR SLUGGISH WILL FOLLOW DOWN
	Pull	---Select---	3.5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE BASE

Service Request

Remington Service

PO Box 700

Madison, NC 27025-0700



Parts and Repairs: P:800-243-9700 F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

18.5"
DN 9/6
3.5
1004

Service Request Number SR00052433		Serial Number / Description 72609 600		Date of Request: 05/07/2013 Date Printed: 05/07/2013	
Customer: BLACKLAND GUN WORKS 12365 US 79 TAYLOR, TX 76574 US		Destination: Arms Services 14 Hoefler Ave Hion, NY 13357 US			
Email: blacklandguns@ecowireless.com		Email:			
Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.					
Reason For Return M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION					
Service Request Section Gun went off, without pulling trigger.					
Parts And Service Details					
Material	Type	Description	Qty Needed	Warranty	Price Disc Amount

Serial Number: 72609
Model: 600

RE00310865

RECEIVED
MAY 16 2013
BY:

T.A. Dirty sticky & rusty.
SEAR WORKS sluggish.
Up. TPA, clean & test und.
small at M/C
#230145

Sub Total: .. .00
Est Sales Tax: .. .00
Grand Total: \$.00

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the





