

Remington Arms Co., Inc.
Product Service
Legal Case #:8717

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
305039	3/18/2013	3/19/2013	3/19/2013				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Darren	Hagins	55904 Evert Rd	Benton City	WA	99320		E.darrenh@clearwire.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		Unknown
S	Fires when safety is pushed off	Concern:1007 Fired on Safe Release		
C				

3/22/13 Per note on SR, fires when safety is pushed off.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	600/6MM REM	n/a	A6515662	EO	10/19/1977
Date Purchased	Where Purchased	Accessories	Original Owner			
	ALL SPORTS SPLY SPOKANE WA	SCOPE BASE,RINGS	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean and test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	26.86	3/22/2013				

3/22/13 Per Ilion, could not duplicate concern. Trigger assm set screws altered, has excess over travel. Replace TPA, clean and test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		3/19/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		18.5" 6MM REM
	Date Code		EO
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	ACTION LOOSE IN STOCK
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.011
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	HAS EXCESSIVE OVER TRAVEL
	Pull	---Select---	4.5#
	Altered	True	SEALANT MISSING
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE BASE, RINGS

Service Request

Remington Service

PO Box 700

Madison, NC 27025-0700



Parts and Repairs: P:800-243-9700 F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

Service Request Number SR00046658		Serial Number / Description A6515662 Model R6152		Date of Request: 02/28/2013 Date Printed: 02/28/2013										
Customer: DARREN HAGINS 55904 EVERETT ROAD BENTON CITY, WA 99320 US		Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US		Email: darrenh@clearwire.net										
Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.														
Reason For Return M240 - BOLT LOCK SAFETY MODIFICATION														
Service Request Section FIRES WHEN SAFETY IS PUSHED OFF.														
Parts And Service Details														
Material	Type	Description	Qty Needed	Warranty	Price Disc Amount									
<div style="display: flex; justify-content: space-between;"> <div> <p>Serial Number: A6515662</p> <p>Model: 600</p> <p>RE00305039</p> </div> <div> <p>RECEIVED</p> <p>MAR 22 2013</p> <p>BY: _____</p> </div> </div>														
<p>THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the</p> <p>could not dup. concern Trig. Assm. set screws a/t. has excess. oven travel. Rep. TPA, clean test and RCP Con 820. +</p> <table> <tr> <td>Sub Total:</td> <td>Q</td> <td>.00</td> </tr> <tr> <td>Est Sales Tax:</td> <td></td> <td>.00</td> </tr> <tr> <td>Grand Total:</td> <td></td> <td>\$.00</td> </tr> </table>						Sub Total:	Q	.00	Est Sales Tax:		.00	Grand Total:		\$.00
Sub Total:	Q	.00												
Est Sales Tax:		.00												
Grand Total:		\$.00												

1/1/2007







