

Remington Arms Co., Inc.
Product Service
Legal Case #:8407

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
294045	12/22/2012	1/2/2013	1/2/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Rodney	McCarl	186 Irvin Hill Rd	Mcveytown	PA	17051		E sjrs@verizon.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006	Altered Adjustments or Components		
S	Has had several accidental discharges	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown
C				
1/9/13 Per note on SR, has had several accidental discharges.cm				

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	600/308 WIN	n/a	89552	CP	4/1/1967
Date Purchased	Where Purchased	Accessories	Original Owner			
		SCOPE BASE	U			

CONCERN: ACCIDENTAL DISCHARGES

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/600/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test under recall						
	Repair/Replacement Cost	Repair/Replacement Date				
	43.86	1/10/2013				
1/10/12 Per Ilion, trigger assm dirty and sticky, set screws altered. Replace TPA, clean and test under recall.cm						

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/2/2013
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4006	Altered Adjustments or Components	
Barrel	Description		18.5" 308 WIN
	Date Code		CP
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.010
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY, STICKY WILL FOLLOW DOWN
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE BASE

Service Request

Remington Service

PO Box 700

Madison, NC 27025-0700



Parts and Repairs: P:800-243-9700 F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

18.5"
CP4/67
2.5#
010

Service Request Number SR00038841		Serial Number / Description 89552 Model		Date of Request: 12/17/2012 Date Printed: 12/17/2012																	
Customer: RODNEY MCCARL 136 IRWIN HILL ROAD MCVEY TOWN, PA 17051 US		Destination: Arms Services 14 Hoefler Ave Bion, NY 13357 US		Email: sjrs@verizon.net																	
Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.																					
Reason For Return M240 - BOLT LOCK SAFETY MODIFICATION																					
Service Request Section HAS HAD SEVERAL ACCIDENTAL DISCHARGES																					
<table border="1"> <thead> <tr> <th>Material</th> <th>Type</th> <th>Description</th> <th>Qty Needed</th> <th>Warranty</th> <th>Price</th> <th>Disc</th> <th>Amount</th> </tr> </thead> <tbody> <tr> <td colspan="8"> Serial Number: 89552 Model: 600 RE00294045 RECEIVED JAN 03 2013 BY: _____ T.A. dinky + sticky, set screws altered. Up TOA, clean test under recall N/C Sub Total: .00 Est Sales Tax: .00 Grand Total: \$.00 </td> </tr> </tbody> </table>						Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount	Serial Number: 89552 Model: 600 RE00294045 RECEIVED JAN 03 2013 BY: _____ T.A. dinky + sticky, set screws altered. Up TOA, clean test under recall N/C Sub Total: .00 Est Sales Tax: .00 Grand Total: \$.00							
Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount														
Serial Number: 89552 Model: 600 RE00294045 RECEIVED JAN 03 2013 BY: _____ T.A. dinky + sticky, set screws altered. Up TOA, clean test under recall N/C Sub Total: .00 Est Sales Tax: .00 Grand Total: \$.00																					
THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the																					