

Remington Arms Co., Inc.
Product Service
Legal Case #:8467

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
295908	1/10/2013	1/11/2013	1/11/2013				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident	Contact, Inc	Richard	Reid	788 Boothbay Rd	Edgcomb	ME	04556		

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Fired when he jacked a shell in the chamber	Cause:4038	Could Not Duplicate Concern	Unknown
C		Concern:1008	Fired on Bolt Closing	
1/18/13 Per note with rifle, sometimes when you jack a shell into the chamber it goes off.cm				

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/A	600/243 WIN	n/a	A6474338	RO	11/14/1977
Date Purchased	Where Purchased	Accessories	Original Owner			
	JERRYS SPORT MONTDALE PA		U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	26.86	1/18/2013				
1/18/13 Per Ilion, could not duplicate concern. Trigger assm set screws altered. Replace TPA, clean, test fire at BLSM program price.cm						

Examination[Remington/CF/A]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/11/2013
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		18.5" 243 WIN
	Date Code		RO
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	SCRATCHES,MARS
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.009
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	HAS EXCESSIVE OVER TRAVEL
	Pull	---Select---	4.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	Other Remington	

1/4/13

Richard Reid

C/O

Contact, Inc.
788 Boothbay Rd.
Edgecomb, ME. 04556

8467

18.5"
20 11/77
4.5#
.009

Dear Sirs

I spoke with a factory approved Gun Smith,
to have this Remington Mohawk-600 repaired.
I told him that sometimes when you jack a
shell into the chamber it goes off.
He said that any safty up grades have to be
done at the factory, and to send the gun to
Remington. Please find enclosed money order
for \$20.00. Please return to above address.

Thank you

Richard Reid

Serial
Number:

A6474338

Model: 600 MOHAWK



RE00295908

RECEIVED
JAN 15 2013

BY:.....

could not sup. concern
T.A. set screws altered.
Rep. TPA, clean test fire
and. BLP for 20. +