Page 1 of 3

PrintDisplay

Remington Arms Co., Inc. Product Service Legal Case #:9390

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

326064 10/31/2013 11/1/2013 11/1/2013

Customer Information

Type Business First Last Street City State Zip Age Contact

Name Name H 304-400-1966

Incident Jennifer Fisher 1931 Oak Ridge Dr Charleston WV 25311 E jenniferfisher06@gmail.com

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause: 4006 Altered Adjustments or Components

onents Unknown

S FSR Concern: 1007 Fired on Safe Release

C

Per SR00062531 Service Request Section, accidental discharge when safety was disengaged. jbi

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial Bbl.
 DOM

 Remington
 CF/BA
 7/7MM 08 REM
 24786
 7693755 DN 9/14/1993

Date Purchased Where Purchased Accessories Original Owner

SIMMONS GUN SPECIALTIES INC U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/7/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement APV APV

Replace trigger, check over and test fire at 50% discount

Repair/Replacement Repair/Replacement
Cost Date

11/5/13: Per Ilion, "trigger sear lift screw altered and trigger contacting trigger guard. Check over, replace trigger assembly, adjust as needed, and test fire at 1/2 normal cost." jbi 11/11/13: I called and left message with quote on Jennifer Fisher's voicemail. jbi 11/12/13: Customer sent letter of approval to Consumer Service. jbi

Examination[Remington/CF/BA]

Part Sub-Part Code Comment

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9390&Type... 12/11/2013

PrintDisplay Page 2 of 3

	Examiner	İ	B.TRAVIS
Examination	Exam Date		11/1/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4006	Altered Adjustments or Components	
	Description		22" 7MM 08 REM
	Date Code		DN
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed	,	
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
Extractor	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
		Select	
		Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
Jaioty	Function	Like new; Functioning	
	Lift	Select	N/A

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9390&Type... 12/11/2013

Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	CONNECTOR NOT UNDER SEAR TRIGGER CONTACTING TRIGGER GUARD
	Pull	Select	N/A
	Altered	True	SEAR LIFT ALTERED
	Sub-Assembly	Other Remington	

Quotation

Remington Service PO Box 700

Estimating Report Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00326064	7693755 Es					e Date:	10/31/2013 11/01/2013 11/07/2013		
Customer: JENNIFER FISHEI 1931 OAK RIDGE CHARLESTON, V	DR		Return To: JENNIFER FISHER 1931 OAK RIDGE DR CHARLESTON, WV 25311 US						
Please Circle One: VISA MC DIS	SCOVER Card No PO Num			Exp	.Date				
Open Account: R	PO Num	iber:							
Approval Signature:).	Time to Cali	<u>_</u>		Date:				
	change, please use the reverse side for you	r comments and i	nark this b	ox.					
	8,7	Problems							
Reported M123 - FORWARD	TO PRODUCT SERVICE FOR INSPECT		3 - FORV	VARD TO PRO	DÚCT SER	VICE FOR	INSPE	CTION	
trigger sear lift screw al	tered and trigg contacting trigger guard. cl	Technician Com heck over,replace	ments trigger ass	sembly,adjust as	needed and	test fire at	I/2 nor	mal c	
Material Type	ESTIMATE (note: C.O.D./Shipping Description	g and Handling		re NOT Include Warranty	ed in this Q Qty		Dist.	Amount	
Material 1 yp	e Description		Qty Needed		From Inv	Price	Disc	Amount	
F305574B Part 4000114 Serv 4000119 Serv	ice GR-SHIPPING & HANDLING		1 1 1	Billable Billable Billable	1 1 1	97.00 17.00 23.00	0	48.50 17.00 11.50	
						· Total:		77.00	
					Est	Sales Tax:		4.62 \$81.62	

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700 F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

22"1 DH9/9

Service Request Number

Serial Number / Description

SR00062531

7693755

Model SEVEN RIFLE

Customer: JENNIFER FISHER

1931 OAKRIDGE DR CHARLESTON, WV 25311 US 9390

Date of Request:

09.24/2013

Date Printed:

09.24/2013

Destination:

Arms Services 14 Hoefler Ave

Ilion, NY 13357 US

Email: jenniferfisher06@gmail.com

Email:

-Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M295 - EVALUATE AND REPAIR SAFETY INSP.

Service Request Section

Accidental discharge when safety was disengaged

when safety is off-gun will not cock safety on-gun will cak - push safety off-gun four

Parts And Service Details

Material

Type

Description

Qty Needed Warranty

Price Disc

Disc Amount

7693755 Model: SEVEN

DECEIVE Nov 0 5 2013

BY:----

Trig. Sear lift screwplt. of
Trig. contacting T. G. check
ouer, Mr. Tik. + ADJ. of
peided treat at 1/2 cost

Sub Total:

.00

Est Sales Tax:

.00

Grand Total:

\$.00

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the









